facilities study:

AUBURN PUBLIC SAFETY BUILDINGS

Engine 2 180 South Main Street

Engine 3 - Central Station / 911 Facilities 550 Minot Street

Engine 5 651 Center Avenue

Police Department 60 Court Street

prepared for: **City of Auburn** 60 Court Street Auburn, Maine

December 15, 2020





Committee Members:

Derek Boulanger	Facilities Manager / Purchasing Agent City of Auburn
Brian Wood	Assistant City Manager City of Auburn
Jason Moen	Chief of Police Auburn Police Department
Robert Chase	Fire Chief Auburn Fire Department
Paul LeClair	911 Director Lewiston /Auburn 911
Tim Hall	Operations Manager Lewiston /Auburn 911

Design Team:



Civil:

M

Megan McDevitt PE Barry Sheff PE

CCE

Mechanical / Elecrtical / Plumbing:

James Hebert PE



Architectural:

Austin Smith AIA Julia Tate AIA Kayla Caron AIA

Table of Contents

Executive Summary	4
Introduction	6
Process	
Existing Conditions	7
Auburn Fire Department Auburn Police Department 911 / Dispatch center	
Schedule	10
Project Cost	12
General Cost Factors Recommended Project Budget Costs	
Appendices	13
Appendix A:Estimate of Probable CostAppendix B:Building Assessment Report CardsAppendix C:Drawings + ProgramAppendix D:Meeting Minutes	

Executive Summary

The charge for the Design Team for the Auburn Public Safety Facilities assessment was a two pronged effort: evaluate the current buildings and to make suggestions for their improvement. The team was to consider the Auburn Police Department Headquarters, three Fire Department stations and a 911 Dispatch Center that serves both Auburn and Lewiston.

Auburn Fire Department Facilities

The team toured and investigated each fire department station (Engine 2, Engine 3- Central, and Engine 5) and assessed the site conditions, building envelope, interior layout, mechanical, electrical and plumbing systems. In addition to these visits and analysis, the fire chief and staff were interviewed to determine how the buildings meet or fall short of their current and future needs.

Each of the three fire department facilities have been well cared for. Maintenance has been performed annually and there are no major failures in the building systems. The three facilities date from the oldest, 1952, to the newest, 1974. Each of the three buildings show obsolescence and have safety, staffing, and program issues. The nature of public safety service has evolved over the last 50 years and these facilities do not support current programs and staffing.

Recommendations

Engine 2

The oldest of the City's three stations, Engine 2 dates from 1952. The living spaces open directly into the apparatus bays, which exposes firefighters to hazardous conditions. The living spaces are undersized and designed to accommodate a single sex staff. Support spaces such as office work stations and fitness areas are non-existent.

The design team studied both a renovation and the construction of a new facility within the existing site boundaries. It was determined that a new facility would have several advantages. It would have easier phasing and have continued, uninterrupted service throughout the duration of construction. The proposed building could be built to modern standards. The proposed building could also have drive-through apparatus bays, greatly improving firefighter safety.

Engine 5

After investigating Engine 5, the design team proposed renovating the existing support spaces and placing an addition on the south elevation of the existing facility. Converting the single sex gang toilet shower areas to multiple single user toilet shower rooms would also aid in bringing the space to more modern standards. Adding an additional bunk room would bring the capacity to 24 beds. Providing work stations for clerical support and a private office for confidentiality when necessary would go a long way to align the program with the space needs.

Auburn Public Safety Facility

There was broad consensus from the committee that locating the Police Department in the Auburn City Hall was a poor fit. The City Hall location does not provide necessary spaces to support the department. It lacks essential support functions such as a secure sallyport, accessible evidence storage, a modern armory, indoor firing range and K9 support. Along with theses issues, there is also a general shortage of space for the police force. Most spaces are undersized for the occupancy such as locker rooms, patrol roll call area and Criminal Investigation Squad Room. There is a shortage of private office space for administration, commanders, support service supervisors and criminal investigators.

The Auburn Police Department was positioned there as a short-term solution and its occupation has lasted more than 11 years. The committee agreed that detailed evaluation of the city hall building was not necessary. Instead, the efforts were focused on what a new location or facility could provide.

A previous study conducted in 2017 programmed a public safety facility that would house a new police department, a central fire station with administration support and also a new 911 Center. The benefits of a shared public safety facility are that there can be a common public entry, lobby, and reception serving both departments. Other shared programs include a community room, training classrooms, a fitness facilities, and emergency operations center.

Through a site design investigation, Central Station on Minot Avenue emerged as the best location for such a facility. To best accommodate all the program elements including site and parking needs, as well as some provision for future expansion, this site lends itself to a logical phasing of the work that would allow for uninterrupted service from both departments.

Central Station, Engine 3, shares the same shortcomings as Engines 2 & 5. Housing and locker areas need to be renovated to accommodate a more diverse fire-fighting team. The existing apparatus bay floor cannot structurally support the AFD tower truck. The design team recommended the addition of a new bay specifically designed for the tower truck.

As part of the proposed Auburn Public Safety Facility, the current 911 Center would be relocated to the new addition allowing for an expanded program and proper program support such as training rooms, locker rooms, and office space for staff.

Introduction

Process

The design team initiated this effort with a kick off meeting with the client to review goals and schedule. The City of Auburn was represented by the city's facility manager, assistant city manager, police chief, fire chief, 911 director and 911 operations managers.

Prior reports, existing conditions material and maintenance records were transferred to the design team for review. The staff of each facility was surveyed to understand the shortcomings of their facility. The design team included civil engineers, architects and mechanical / electrical / plumbing engineers. The design team produced a written program and outlined the major issues in each facility based upon information gathered during the site visits. These documents were reviewed by the committee for accuracy.

The committee and design team scheduled workshop sessions at roughly three-week intervals. In each workshop the design team presented different design alternatives for review by the committee. Solutions were narrowed and refined for the following meeting. As an example, for Engine 2, a 2,800 square foot facility located on South Main Street, the design team investigated a renovation and addition to the existing building. A new free-standing facility, adjacent to the existing on the same lot, was also considered. The advantages, disadvantages and costs of each approach were presented to the committee for a decision. This iterative process continued for each facility until the committee reached consensus.

Existing Conditions

Auburn Fire Department Existing Conditions

A general summary of the three AFD facilities finds they are all of similar condition dating from 1952 to 1974. The facilities have been well maintained and upgraded when possible. Each of the three AFD buildings have had roof replacements within the last ten years. Systems have been upgraded, such as conversions to LED lighting and natural gas as a fuel source. Buildings are kept in good working order and when failures occur they have been promptly addressed.

As a rule, buildings approaching 50 years of age should be evaluated to determine if they are beyond their useful life. In most cases, the cost of maintenance can determine that a replacement building is necessary. Some conditions of the original building cannot be corrected or brought up to current standards. For example, features such as slab and foundation insulation cannot be retrofitted since they are not physically accessible.

New or renovated facilities should account for long term department planning. The assignment of EMS staff and units to Station 2 should be accounted for in facility planning. In addition, the relocation of the tower truck from Station 5 to Station 3 should also be accommodated.

While the facilities have been well maintained, as originally designed, they have become obsolete and do not accommodate current public safety programs. Fire Department leadership noted these major shortcomings in all AFD facilities.

•Firefighter's exposure to hazardous materials

Living quarters open directly into the apparatus bays, exposing firefighters to diesel exhaust fumes. Contaminated gear and equipment are not properly separated from living spaces. Cancer is a leading cause of death for firefighters and the station should provide protection from all unsafe exposure.

•Accommodating diversity

All three facilities were built to accommodate single sex firefighters. Toilet and showers were designed for males only and in gang shared situations. Today's fire departments are diverse and should be able to accommodate a flexible combination of staff of different sexes. A mixture of individual user toilets and showers provide the greatest flexibility and privacy.

•Staffing requirements

For comfort, sanitation, and ease of use, each staff member should have a dedicated bed for their own use.

•Office support

Current public safety procedure requires written reports after each call.

There is a shortage, or in some cases, a complete lack of office space for work stations for report filings. The dayroom or bunk areas are used at Engine 2 for reporting. Engine stations 2 and 5 lack a private office for confidential conversations. Stations also provide service directly to the public for purposes such as burn permits, and thus require work space for these and other interactions with the public.

•Modern amenities and staff support

Fitness rooms are essential to the health of firefighters. Staff need access to a purpose built dedicated room with a variety of equipment for each station.

Existing dayroom kitchens are outdated and should be modernized and upgraded.

•Storage

Apparatus bays are cluttered with extra gear, exercise equipment, appliances, vending machines, and paper files. Dedicated proper storage should be provided to keep the bays clear and free of obstructions and separate contaminated gear from living quarters.

Auburn Police Department Existing Conditions

The APD is currently housed in the Auburn City Hall. This location was considered a short-term occupation with a time limit of five years. APD have been in this location for 11 years now, and the building seriously hinders their ability to provide service. The design team purposely did not evaluate the condition of the building, but instead considered how the Police Department program was compromised by the facility.

Staff parking spaces are not secure and are mixed with other City Hall parking. Both evidence storage and vehicle impound areas are remote from City Hall and require staff to traverse the city parking garage. The vehicle impound area lacks a secure perimeter and is limited in space. Impounded vehicles share space with other police vehicles such as motorcycles and ATVs. Evidence storage is conducted by one assigned employee whose office is on the third floor of City Hall, remote from the primary entrance. Evidence storage in this location has both limited headroom and capacity and inadequate HVAC

Patrol areas need adequate support spaces such as locker rooms and shower areas. The facilities also have had to adapt to current staffing which has a mixtures of genders. Programs such as a fitness room and armory have had to be converted from found space, and should be accommodated in more appropriate purpose-built space. Departments are separated from one another on first and third floors that make it more difficult to communicate effectively. Patrol and roll call areas are not adjacent to the exterior, which is a more desirable location. Criminal investigation needs interview rooms which are accessible to the public without entering into secure areas.

There is a general shortage of office space for the police force. The police administration, support services supervisors, criminal investigation supervisors, and commanders all require private office spaces. There should also be dedicated conference rooms for the police administration. Currently conference rooms are shared with other departments at City Hall. Adequate open work stations that are aligned with the current staffing and also some provision for future expansion of the department, should be provided.

The facility lacks many programs and support spaces that are expected of a department this size. The current building does not provide a sally port for secure transition from vehicles to prisoner processing. There is no booking area, holding area or space for intoxilyzer. There should also be a designated toilet for use by prisoners.

The department requires purpose built spaces rather than adapting the office space of City Hall to fit their needs. Secure and accessible spaces for the armory, patrol and riot gear are needed. An indoor firing range would be a major benefit to the department and would eliminate travel for training and qualification of officers. A new facility could also house a kennel and office space for a K9 officer. Other support spaces could include short term sleeping spaces for between shift sleeping.

911 Center Existing Conditions

The 911 Center and dispatch is housed in a shared facility between the Cities of Auburn and Lewiston. It is currently located in the lower level of Central Station (Engine 3) adjacent to the fire department boiler room and maintenance garage. There is a shortage of office space for the support staff such as IT Director, IT Specialist, Operations Manager, and Office Manager.

Additional support spaces are needed such as training rooms, expanded locker area, and a space for secure storage of records. The Dispatch space itself needs to account for growth and the possibility of adding additional consoles when necessary.

One major issue for the staff is the lack of windows and access to natural light. As it is located in the basement, it has a bunker-like feeling. Business with the public is also conducted here and requires a secure reception area that is both visible and accessible.

Schedule

Addressing all of the existing Auburn Public Safety Facilities is a major undertaking. There are roughly 43,000 square feet distributed across four different locations. To compound the difficulty, all levels of public safety service need to be maintained in constant operation. The client and design team arrived at an approach that requires 4 ½ years for completion.

As the oldest of the Auburn stations, Engine 2, dating from 1952, was given the highest priority. The committee had investigated a renovation / addition versus a new freestanding facility. A new building on the site had the advantage of no disruption to service and ease of transition between existing and new construction. The new facility would be designed to house a future EMT unit. As such, it would be significantly larger than the existing station. Design, permitting, and construction is anticipated to take 21 months.


Upon completion of Engine 2, the Fire Department Administration would temporarily move from Central Station to the new Engine 2 Station. Fire Department offices would occupy the future EMT areas. Construction would start on a major addition to Central Station / Engine 3 for the ultimate conversion into the Auburn Public Safety Facility. Approximately 16,000 square feet of new construction for new Police Department, new 911 Center and shared Lobby / Fitness spaces would be added to the east side of the existing building. The five apparatus bays of each building would remain operational. The existing building would also maintain the existing firefighter housing and 911 Center. This phase of construction is anticipated to take 12 months.

Upon completion of the east side addition, the Police Department and 911 Center would relocate to the new addition. 2 months is allotted in the schedule for this transition. With this transition complete, the existing Station 3 would be thoroughly renovated and a 24 foot apparatus bay would be added to the west side of the building. This new bay would be sized and structured to accommodate the relocation of the Tower Truck to Station 3. The lower level and old 911 Center would be converted to support space including a three lane, 25-yard, indoor firing range for the Police Department. Final site work would also be completed in this stage of construction. This final phase would last 9 months.

Engine 5 renovation and addition to the building would take approximately 10 months and could be done independent of other stations.

The overall project schedule follows, inclusive of the need and timing for site investigations, design and engineering, approvals and permitting, bidding and negotiations.

Schedule



Key	
(A)	Pre-design Investig geotechnical repor
B	Design /Constructi
Ô	Bidding /Negotiati
D	Construction New
E	Demolition Existing
Ē	Relocate Fire Depa
G	Design / Construct Facility at Central S
H	Bidding / Mobilizo
\bigcirc	Construction Phase Center, New public
J	Relocation of 911
K	Renovations / Add level, Phase Two
L	Final Site Work. R Relocate Tower Tru
\bigotimes	Design / Construct
\mathbb{N}	Bidding /Negotiati
0	Construction Renov

Fourth Year	Fifth Year
Engine 5	
\bigcirc	
	()
Task	Duration
ation. Site Survey, wetlands delineation,	4 months
t. on & Bid Documents New Engine 2	9 months
on	2 months
Engine 2	10 months
Engine 2 / Complete Site Work	2 months
rtment Administration to New Engine 2	1 month
ion & Bid Documents for New Public Safety Station – Phase One	12 months
ition Phase One	2 months
One, New Police Department, New 911 c entry and lobby, New Shared Fitness Center	12 month er
Center	2 month
ition to Fire Department Conversion of lowe	r 7 months
elocate Fire Department Administration. ck	2 months
ion & Bid Documents Addition to Engine 5	9 months
on Engine 5	2 months
ration and Addition Engine 5	10 months

Project Costs

Given the depth of this planning effort, all proposed solutions were at the conceptual level and general in nature. Projections of project costs are preliminary as they are based on conceptual design solutions. Project costs are included in greater detail in Appendix A.

•Due to the conceptual nature of the design solutions, the construction costs have been based upon historic cost per square foot. Recently completed Police and Fire Department facilities within the State of Maine were used as a starting point and the basis for building costs.

•Premiums were added to cost estimates for intensive, specialized areas such as the 911 dispatch area and indoor firing range. These were based upon peer facility costs within the state of Maine.

•Soft costs such as site survey, geotechnical investigation, architectural / engineering fees, approvals, permitting, testing, inspections were also factored into the project cost.

•Furniture fixture and equipment were also accounted for as the new expansion will require new furniture. As a starting point an estimated cost per square foot was used for new furniture allotment.

•Contingencies were included for both the design and for the Owner's use in construction.

•Acquisition of property and moving costs were not included in the cost projections. As scheduled, temporary or modular offices would not be required.

•Engine 2 was considered and estimated in two ways; renovation / addition versus a new freestanding building. Final cost projections include the new building only.

•Cost of the new 911 Center was included within the cost of the proposed Auburn Public Safety Facility. A separate cost analysis determined what portion of the building cost could be assigned to the 911 Center.

•Base project cost projections were targeted for the year 2022. An inflation factor of 3.5% was used

	Site Investigations & Surveys 2021	Construction & Soft Costs 2022	Construction & Soft Costs 2023	Construction & Soft Costs 2024	Construction & Soft Costs 2025
Engine 2: New Construction	\$40,000	\$2,626,471	\$2,718,397	\$2,813,541	\$2,912,015
Engine 5: Renovation & Addition	\$40,000	\$2,684,458	\$2,778.414	\$2,875,659	\$2,976,307
Engine 3: Conversion of Central Station / 911 to New Public Safety Facility	\$120,000	\$18,418,449	\$19,063,095	\$19,730,303	\$20,420,864
TOTAL	\$200,000	\$23,729,378	\$24,559,906	\$25,419,503	\$26,309,186

-

Appendices

Appendix A: Appendix B: Appendix C: Appendix D:

Estimate of Probable Cost Building Assessment Report Cards Drawings + Program Meeting Minutes

Appendix A

Estimate of Probable Cost

New Public Safety Facility

Renovation and Addition

Auburn Public Safety Facility. Renovation & Addition Conceptual Design Cost Worksheet.	Area	Cost/SF	Cost	Notes
Part One: Base Price	7 Hou	0030/01	0031	
Renovations	23,633	180	4,253,940	SF cost based upon Ledgewood Construction historic data
New Addition / New Construction	27,551	305	8,403,055	SF cost based upon Ledgewood Construction historic data
Site Costs			2,400,000	Shared site cost prorated to percentage of area
Special Construction Costs			365,000	911 / Dispatch Technology
Contractor's OH&P				Carried in the construction cost
Subtotal			15,421,995	2022 Construction Cost
Design Contingency				Carried in the construction cost
SUBTOTAL Estimated Construction Costs				
Part Two: FFE, Fees, and Services				
Architecture/Engineering Fees			1,233,760	8% BGS "B" Rate for New Construction
Approvals and permitting, SFM, PB & DEP			84,000	Assumed waiver of Building Permit Fee
Soils/Borings/Geotech Engineering			20,000	allowance
Materials Testing Controlled Inspections			22,000	Per IBC 2012
Utility Fees			18,000	allowance
SUBTOTAL: Fees and Services			1,377,760	
Part Three: Administrative Costs				
Furnishings, Fixtures, Equipment			354,495	Allowance of \$15 persf for Office/ Bunk /Day Room
Insurance/Legal			28,000	Builders Risk, Allowance
Boundary/Topo Survey				Survey
Owner's Contingency			1,542,200	Recommended 10% of Const Cost
Construction Clerk / part time			48,000	
SUBTOTAL: Administrative Costs			1,972,695	
TOTAL			18,772,449	2022 Project Cost
			19,429,485	2023 Project Cost at 3.5% inflation
			20,109,517	2024 Project Cost at 3.5% inflation
			20,813,350	2025 Project Cost at 3.5% inflation

New Public Safety Facility

Auburn Public Safety Facility Renovation & Addition Conceptual Design Cost Worksheet.	Area	Cost/SF	Cost	Notes
Part One: Base Price				
New Addition / New Construction	4190	305	\$ 1,277,950	SF cost based upon Ledgewood Construction historic data
Portion of Building Infrastructure			66,856	
Site Costs			172,529	Shared site cost prorated to percentage of area
Special Construction Costs			365,000	Dispatch connections and equipment
Contractor's OH&P				Carried in the construction cost
Subtotal			1,882,335	2022 Construction Cost
Design Contingency				Carried in the construction cost
SUBTOTAL Estimated Construction Costs			1,882,335	
Part Two: FFE, Fees, and Services				
Architecture/Engineering Fees			150,587	8% BGS "B" Rate for New Construction
Approvals and permitting, SFM				SFM only,
Soils/Borings/Geotech Engineering				allowance
Materials Testing Controlled Inspections				Per IBC 2012
Utility Fees				allowance
SUBTOTAL: Fees and Services			150,587	
Part Three: Administrative Costs				
Furnishings, Fixtures, Equipment			62,850	Allowance of \$15 per sf for Office
Insurance/Legal			18,000	Builders Risk, Allowance
Boundary/Topo Survey				Survey
Owner's Contingency			188,234	Recommended 10% of Const Cost
Construction Clerk / part time				
SUBTOTAL: Administrative Costs			269,084	
TOTAL			2,302,005	2022 Project Cost
			2,382,575	2023 Project Cost at 3.5% inflation
			2,465,966	2024 Project Cost at 3.5% inflation
			2,552,274	2025 Project Cost at 3.5% inflation

Note: This budget is prepared by SA as a planning tool for reference only and should not take the place of a comprehensive project budget by the Owner. This budget may not reflect all associated project costs.

911 Dispatch Center

Engine 2

New Construction

City of Auburn Fire Department - Engine 2 Renovation & Addition Conceptual Design Cost Worksheet.	Area	Cost/SF	Cost	Notes
Part One: Base Price				
New Addition / New Construction	6,496	290	1,883,840	SF cost based upon Ledgewood Construction historic data
Site Costs			195,000	Woodard & Curan
Special Construction Costs				
Contractor's OH&P				Carried in the construction cost
Subtotal			2,078,840	2022 Construction Cost
Design Contingency				Carried in the construction cost
SUBTOTAL Estimated Construction Costs				
Part Two: FFE, Fees, and Services				
Architecture/Engineering Fees			166,307	8% BGS "B" Rate for New Construction
Approvals and permitting, SFM			14,000	SFM only, Assumed waiver of Building Permit Fee
Soils/Borings/Geotech Engineering			4,000	allowance
Materials Testing Controlled Inspections			6,000	Per IBC 2012
Utility Fees			10,000	allowance
SUBTOTAL: Fees and Services			200,307	
Part Three: Administrative Costs				
Furnishings, Fixtures, Equipment			97,440	Allowance of \$15 persf for Office/Bunk /Day Room
Insurance/Legal			18,000	Builders Risk, Allowance
Boundary/Topo Survey				Survey
Owner's Contingency			207,884	Recommended 10% of Const Cost
Construction Clerk / part time			24,000	
SUBTOTAL: Administrative Costs			347,324	
TOTAL			2,626,471	2022 Project Cost
			2,718,398	2023 Project Cost at 3.5% inflation
			2,813,542	2024 Project Cost at 3.5% inflation
			2,912,016	2025 Project Cost at 3.5% inflation

Engine 2

Renovation and Addition

City of Auburn Fire Department - Engine 2 Renovation & Addition Conceptual Design Cost Worksheet.				Notes
	Area	Cost/SF	Cost	
Part One: Base Price				SF cost based upon Ledgewood Construction historic
Renovation of Existing Spaces.	2,658	180	478,440	data SF cost based upon Ledgewood Construction historic
New Addition /New Construction	3,800	290	1,102,000	SF COST based upon Ledgewood Construction historic
Site Costs			110,000	
Special Construction Costs				
Contractor's OH&P				Carried in the construction cost
Subtotal			1,690,440	2022 Construction Cost
Design Contingency				Carried in the construction cost
SUBTOTAL Estimated Construction Costs				
Part Two: FFE, Fees, and Services				
Architecture/Engineering Fees			135,235	8% BGS "B" Rate for New Construction
Approvals and permitting, SFM			14,000	SFM only, Assumed waiver of Building Permit Fee
Soils/Borings/Geotech Engineering			4,000	allowance
Materials Testing Controlled Inspections			6,000	Per IBC 2012
Utility Fees			10,000	allowance
SUBTOTAL: Fees and Services			169,235	
Part Three: Administrative Costs				
Furnishings, Fixtures, Equipment			59,658	Allowance of \$15 persf for Office/Bunk /Day Room
Insurance/Legal			18,000	Builders Risk , Allowance
Boundary/Topo Survey				Survey
Owner's Contingency			169,044	Recommended 10% of Const Cost
Construction Clerk / part time			24,000	
SUBTOTAL: Administrative Costs			270,702	
TOTAL			2,130,377	2022 Project Cost
			2,204,940	2023 Project Cost at 3.5% inflation
			2,282,113	2024 Project Cost at 3.5% inflation
			2,361,987	2025 Project Cost at 3.5% inflation

Engine 5

Renovation	and	Addition
------------	-----	----------

•				
Engine 5. Renovation & Addition Conceptual Design Cost Worksheet.	Area	Cost/SF	Cost	Notes
Part One: Base Price				
Renovation of Existing Spaces.	7,304	180	1,314,720	SF cost based upon Ledgewood Construction historic
New Addition /New Construction	1,727	290	500,830	data SF cost based upon Ledgewood Construction historic data
Site Costs			355,000	Uala
Special Construction Costs				
Contractor's OH&P				Carried in the construction cost
Subtotal			2,170,550	2022 Construction Cost
Design Contingency				Carried in the construction cost
SUBTOTAL Estimated Construction Costs				
Part Two: FFE, Fees, and Services				
Architecture/Engineering Fees			173,644	8% BGS "B" Rate for New Construction
Approvals and permitting, SFM & PB			28,000	SFM & PB only, Assumed waiver of Building Permit Fee
Soils/Borings/Geotech Engineering			2,000	allowance
Materials Testing Controlled Inspections			6,000	Per IBC 2012
Utility Fees			12,000	allowance
SUBTOTAL: Fees and Services			221,644	
Part Three: Administrative Costs				
Furnishings, Fixtures, Equipment			33,209	Allowance of \$15 persf for Office/Bunk /Day Room
Insurance/Legal			18,000	Builders Risk, Allowance
Boundary/Topo Survey				Survey
Owner's Contingency			217,055	Recommended 10% of Const Cost
Construction Clerk / part time			24,000	
SUBTOTAL: Administrative Costs			292,264	
TOTAL			2,684,458	2022 Project Cost
			2,778,414	2023 Project Cost at 3.5% inflation
			2,875,659	2024 Project Cost at 3.5% inflation
			2,976,307	2025 Project Cost at 3.5% inflation

	struction and Costs, 2022	 Construction and Soft Costs, 2023 Construction and Soft Costs, 2024		Construction and Soft Costs, 2025		
Engine 2, New Construction	\$ 2,626,471	\$ 2,718,397	\$	2,813,541	\$	2,912,015
Engine 5, Renovation and Addition	\$ 2,684,458	\$ 2,778,414	\$	2,875,659	\$	2,976,307
Conversion of Engine 3 to Public Safety Facility	\$ 18,418,449	\$ 19,063,095	\$	19,730,303	\$	20,420,864
Total	\$ 23,729,378	\$ 24,559,906	\$	25,419,503	\$	26,309,186

Auburn Public Safety Facilities - Summation

Appendix B

Building Assessment Report Cards

Appendix B:

BUILDING ASSESSMENT REPORT CARD AUBURN PUBLIC SAFETY FACILITIES Assessment Study

NO G

F

F F

P

NA

NA

NA

P

NO

8

G

G

NO

G/F

NO

Е

F

F

F

G

G

N

N

NA

NA

NA

NA NC

NC

P

G

G

NA

G

В

Roof Material Building Ir Floors - Level 1

Walls - Level 1

Stairs Elevators/Escalators

Ceilings - Level 1

opecialty Systems

AHU/Controls

Chiller/Controls

HVAC Distribution & Controls

Boiler/Heat Exchange/Controls

Pumps/Motors/Compressors

Plumbing Systems/Fixtures

Building Electrical

Fire Alarm System Emergency Power/Lighting Systems

Lighting Systems

Power Wiring

Tel/Data Systems

ME/ADA

Exterior Doors

Interior Doors Horizontal Circulation (Corridors)

Toilet Rooms Drinking Fountains

Site Lighting

Signage

Security Systems / Credentialed Acce

Horizontal Circulation (Ramps)

Vertical Circulation (Elevators)

Site Drainage / Permeability Stormwater Management

Wastewater Management

Parking / Paved Surfaces

Specialty Systems Vegetation

Vertical Circulation (Stairs)

Electrical Distribution

Fire Sprinkler/Standpipe Systems

Doors/Frames/Hardware Built-in Furnishings

Building Name: Address: Construction year: Occupancy Group: Floors Above / Below Grade: Gross Square Footage:	Engine 2 180 South Mai 1952 Office 1 / 0 ¹ 2,658 sf	in Street Auburn, ME		Legend: E G F	Excellent Good Fair	Generally at a 'near new' condition. Appropriate funding and continued routine maintenance will be required to maintain this level. Generally at a acceptable condition, with some observable wear. Appropriate fund continued routine maintenance will be required to maintain this level. Generally at a minimal acceptable condition, with significant wear. Improvements involving areater than routine maintenance, and additional funding required.
						Conditions are below acceptable level and require substantial funding and/or
Building Component	Condition	Notes		P	Poor	considerable maintenance efforts to be improved or replaced.
Building Exterior					_	
Foundations (below grade)	NO			NA	Not Applicable	
Foundations (above grade)	F					
Exterior Walls - North (above grade)	F			NO	Not Observed	
Exterior Walls - East (above grade)	F					
Exterior Walls - South (above grade)	F					
Exterior Walls - West (above arade)	F		-			
Building Framing	NO					
Windows/Louvers	F	Vinyl windowsapproaching endof useful life				
Doors/Frames/Hardware	Р	Original doors are not fire rated or properly sealed				
Roof Structure	NO					
	-					

Legend: C

Compliant

PC Partially Compliant

NC Non-Compliant

Not Applicable

Not Observed

Conforms with the most current version of Building Code of Maine and ICC/ANSI A117.1 ADA $% \mathcal{A} = \mathcal{A} = \mathcal{A} = \mathcal{A}$

Partially confirms with the most current version of the Building Code of Maine or ICC/ANSI A177.1 ADA.

Does not conform with the most current version of the Building Code of Maine or ICC/ANSI A177.1 ADA

Roof Replacement within the last 6 years

Doors from Living Area to Apparatus bays lack fire rating

No ventilation in garage, box fan typically used in bathroom/shower/laundry area. Apparautus Bay Heater added in 2017

Apparautus Bay Heater added in 2017 Window AC units are used for cooling.

Boiler less than 10 years old.

No sprinkler system installed. Fixtures and plumbing piping are dated - some new piping has been installed in support of bailer work

boiler work.

No overall building system observed. Emergency power from dedicated natural gas generator (2018). No lighting control for energy efficiency. Much of the existing distribution is beyond it's usaful life. Much of the existing distribution is beyond it's usaful life. Phone systems are dated, but functioning as designed. Functioning as intended

Functioning as intended.

Doors lack lever hardware

Doors lack lever hardware

Lack of ADA signage

Owner reports site drainage is poo

Building mounted lighting only Staff and public parking not defined. Appa bay lacks drive through approach.

GE	NERA	LNC	TES:	

1. Slab at Services Room is depressed below grade

Appendix B:

BUILDING ASSESSMENT REPORT CARD AUBURN PUBLIC SAFETY FACILITIES Assessment Study

/ asossinoin ology	
Building Name:	Engine 3 [CENTRAL STATION]
Address:	550 Minot Avenue Auburn, ME
Construction year:	1972
Occupancy Group:	Office
Floors Above / Below Grade:	3 / 11
Gross Square Footage:	23,633 SF

Building Component	Condition	Notes
Building Ederior	Condition	INOTES
Foundations (below grade)	NO	
	F	Structural assessment of bay slabs and coating application completed in 2015. Bay slabs are at their designed load
Foundations (above grade)	Р	capacity. Brick veneer wall with CMU back-up, No Insulation
Exterior Walls - North (above grade) Exterior Walls - East (above grade)	P	Brick veneer wall with CMU back-up, No Insulation Brick veneer wall with CMU back-up, No Insulation
Exterior Walls - South (above grade)	P	Brick veneer wall with CMU back-up, No Insulation
Exterior Walls - West (above grade)	P	Brick veneer wall with CMU back-up, No Insulation
Building Framing	NO	
Windows/Louvers	P	Original windows to building in most cases
Doors/Frames/Hardware	P	Uninsulated and poorly weatherstripping
Roof Structure	NO G	
Roof Material	G	Roofing replaced in 2010
Building Interior		
Floors - Level 3	G	
Floors - Level 2	G	
Floors - Level 1	G	Bay floor recoated in 2015
Walls - Level 3	G	
Walls - Level 2	G	
Walls - Level 1	G	ATC replaced in 2016
Ceilings - Level 3	G	ATC replaced in 2016 ATC replaced in 2016
Ceilings - Level 2 Ceilings - Level 1	F	
Ceilings - Level 1 Doors/Frames/Hardware	· · ·	
	F	Watch desk area and reception restroom renovated in 2019
Built-in Furnishings	F	Non-code compliant stair railing
Stairs	NA	Non-code compliant stair railing No elevator, No HC access to upper floor levels
Elevators/Escalators	NA	INO elevator, NO FIC access to upper floor levels
Specialty Systems		
Building Systems		
HVAC Distribution & Controls	F	Repairs/updates completed to extend orginal equipment lifespan, but is in need of complete replacement.
AHU/Controls	F	Repairs/updates completed to extend orginal equipment lifespan, but is in need of complete replacement.
Chiller/Controls	G	New 4 and 2 ton units installed within last five years
Boiler/Heat Exchange/Controls	E/G	1 of 2 main boilers replaced in 2020 - second boiler should be replaced similarly within next 5 years
Pumps/Motors/Compressors	G/F	Some equipment replaced as part of 2014 heating system upgrade and 2020 boiler upgrade. Significant older equipment and distribution still remains in need of replacement.
Fire Sprinkler/Standpipe Systems	Not observed	Building does not appear to be sprinklered.
Plumbing Systems/Fixtures	F	Fixtures and plumbing piping are dated - some new piping has been installed in support of boiler work.
Specialty Systems	F	Existing underground storage tank nearing expiration and must be removed/repaired/replaced
Building Electrical		
	F	No overall building fire alarm system observed. Local smoke/heat detectors only.
Fire Alarm System	G	23,633
Emergency Power/Lighting Systems	_	
Lighting Systems	E	Lighting converted to LED in 2016.
Electrical Distribution	G	
Power Wiring	G	
Tel/Data Systems Specialty Systems	G	E911 support systems appear fully functional.
Specialty Systems / Credentialed Access	G	E711 support systems uppedrivity tonchondi.
ME/ADA		
Exterior Doors	NC	Excessive thressholds non-compliant knob hardware
Interior Doors	NC	Non-compliant knob hardware, Inadequate door clearance
Horizontal Circulation (Corridors)	PC	
Horizontal Circulation (Ramps)	NA NC	Non-compliant railings
Vertical Circulation (Stairs) Vertical Circulation (Elevators)	NA	comprom rentitys
Toilet Rooms	NC	Lack of ADA facilities
Drinking Fountains	NC	
Signage	NC	Lack of ADA signage
SITEWORK / CIVIL		
Site Drainage / Perme-Lilit.	G	
Site Drainage / Permeability Stormwater Management	G	
Wastewater Management	G	
Site Lighting	NA	Building mounted lighting only
Parking / Paved Surfaces	G	Rear driveway reconstruction and paving in 2019
		Training building upgraded in 2017, Underground fuel tanks
Specialty Systems	G	should be upgraded within ten years.
Vegetation	G	<u> </u>
		•

Legena:		
E	Excellent	Ger mai
G	Good	Ger con
F	Fair	Ger invo
Р	Poor	Cor con
NA	Not Applicable	
NO	Not Observed	

and.

Generally at a 'near new' condition. Apprapriate funding and continued routine maintenance will be required to maintain this level. Generally at a acceptable condition, with some observable wear. Appropriate funding an continued routine maintenance will be required to maintain this level. Generally at a minimal acceptable condition, with significant wear. Improvements involving greater than routine maintenance, and additional funding required. Conditions are below acceptable level and require substantial funding and/or considerable maintenance efforts to be improved or replaced.

C C	Conforms with the most current version of Building Code of Maine and ICC/ANSI A117.1 ADA
PC Partially Compliant	Partially confirms with the most current version of the Building Code of Maine or ICC/ANS A177.1 ADA.
Non-Compliant	Does not conform with the most current version of the Building Code of Maine or ICC/ANSI A177.1 ADA
Not Applicable	
Not Observed	

Appendix B:

BUILDING ASSESSMENT REPORT CARD AUBURN PUBLIC SAFETY FACILITIES

Assessment Slucy
Building Name:
Address:
Construction year:
Occupancy Group:
Floors Above / Below Grade:
Gross Square Footage:

	Engine 5
	651 Center Street Auburn, ME
	1974
	Office
ade:	1/0
	7,300 sf

Stairs NA No Stairs Elevators/Escalators NA No Elevator Specially Systems NA No Elevator Building Systems NA No Elevator ANA No Elevator Specially Systems No Elevator Building Systems NA No Elevator Specially Systems No Elevator HVAC Distribution & Controls F HVAC zones are a challenge to monitor due to 3/4 height walls. Hold Activators Activators Activators Appear original. Chiller/Controls F Existing distribution/Activators Appear original. Air conditioning provided by window units. Boiler/Heart Exchange/Controls G Replaced with Natural Cas in 2016. Boiler and pumps replaced in 2013 Pumps/Motors/Compressors G New water line to building and upprades to front end plumbing strates. Plumbing Systems/Flotures G New water line to building and upgrades to front end plumbing service. Energency Power/Lighting Systems E Emergency power from dedicated natural gas generator (2018). Lighting Systems E Lighting converted to LED in 2016. Electrical Distribution G Security Systems <th>Gross Square Footage:</th> <th>7,300 sf</th> <th></th>	Gross Square Footage:	7,300 sf	
Notice Service NO Fordation (above grade) F Spacing Walk - North (above grade) F Extrice North - North (above grade) F Extrice Doon P Extrice North - North (above grade) F Extrice North NO Roof Naterial G Extrice North NO Roof Naterial F Extrice North NO Roof Naterial F Extrice North NO Roof Naterial F Extrice North Roof Naterial NO Roof Naterial F Extrice Naterial F Extrice Nath Roof Naterial	Puilding C	Carabi	Nett
Faculation (above grade) F Spalling and patching of slob at boy door. Extrict Walk - North (above grade) F Extrict Walk - South (above grade) F Extrict Walk - North (above grade) F Extrict Walk - North (above grade) F Extrict Walk - North (above grade) F Structural evolution for snow drifting should be considered. Windows/Loovers P Majority of vindows or gigat be building and perform uninstabulated with poor websites and and units websites and	Building Component	Condition	Notes
Faculation (above grade) F Spalling and patching of slob at boy door. Extrict Walk - North (above grade) F Extrict Walk - South (above grade) F Extrict Walk - North (above grade) F Extrict Walk - North (above grade) F Extrict Walk - North (above grade) F Structural evolution for snow drifting should be considered. Windows/Loovers P Majority of vindows or gigat be building and perform uninstabulated with poor websites and and units websites and	Foundations (below grade)	NO	
Earcier Wolk - Kenft (abore grode) Editor: Wolk - Eart (abore grode) Editor: Wolk - Kenft (abore grode) F Editor: Wolk - West (abore grode) F Editor: Doon			Spalling and patching of slab at bay doors
Extence Verbal Extence Verbal Sector Extence Verbal Sector F Exponed Weinig / Contain Extence Verbal Sector F Sector S		F	,
Entery Walk - Souh (above grode) F Espaced Wring / Conduit Extrice Walk - Weak (above grode) F Structural enduction for some drifting should be considered. Building Transing. P Majority of virulewas origical to building and parfore poor weaking should be considered. Building Transing. P Doors at south elevation hore weaking should be considered. Building Transing. P Doors at south elevation hore weaking should be considered. Roof Structura NO NO nor south elevation hore weaking should be considered. Roof Material O Roofing replaced in 2017 Notational Walks - Level 1 F CMU partitions of Stepping area do no extend full height Walks - Level 1 F CMU partitions of Stepping area do no extend full height Statistic Condons NA No Stein Doors / Transi Arg F Casework and countertops are in worn condition Statistic Condons NA No Stein PACD Directation & Controls F HVAC zones are a challings to monite due to 3/4 height walk. Attended Statistic & Controls F HVAC zones are a challings to monite due to 3/4 height walk.		F	
Extrict Weble - Webl (above grade) F Building Framing F Structural evolution for struct driving should be considered. Microired structure driving should be considered. Windows/Looves P Does at social evolution for structure driving should be considered. Does at social evolution have extrine tables and are uninsulated with poor wether seeling. Roof Structure P Does at social evolution have extrine tables and are uninsulated with poor wether seeling. Roof Structure F CMU partitions of Steeping area do no extend full beight Webs. Level 1 F CMU partitions of Steeping area do no extend full beight Webs. Level 1 F CMU partitions of Steeping area do no extend full beight Webs. Level 1 F Conservation and area of the social social social evolution for social social social social social social social evolution for social socis		F	Exposed Wiring / Conduit
Bulding Froming - considered. Windows/Louvers P Majority of windows original to bulding and parform poorly hemmally. Exterior Doors P Doors at such devotion how exterior steps and an unisubated with poor worther saching. Roof Material G Roofing replaced in 2017 Wildles toward P CAU partitions of Stepping area do no extend full height Walk - Level 1 F CAU partitions of Stepping area do no extend full height Walk - Level 1 P Water steins in ACT of office. ACT celling replacement in 2016 Doors/Transul/Standbarge P Casework and countertops are in worn condition Stars NA No Elevator PACE Distribution & Control. F HVAC zones are a challenge to monitor due to 3/4 height wills. Paller Systems NO Air controling provided by window units. Punder Systems NO Air controling provided by window units. Punge/Motors/Compressors G Replaced with Natural Case. in 2016. Boiler and parts in place. Fire Sprinkler/Standbarg Systems E Energreyor power fuel doctaced natural gas any stem in place. Powary/Lighting Systems E <t< td=""><td></td><td>F</td><td></td></t<>		F	
Window Jacows P poorly hemally. Exercic Doors P Doors at such elevation one such sites staps and one uninsubated with poor weathersacking. Roof Structure NO Roofing replaced in 2017 Roofing replaced in 2017 Roofing replaced in 2017 Withing Interior F CMU partitions of Skepping area do no autend full height Wales - Level 1 F CMU partitions of Skepping area do no autend full height Callings - Level 1 F CMU partitions of Skepping area do no autend full height Doors/Transult-facebase P Casework and countertaps are in worn condition Star. NA No Elevator Star. NA No Elevator PMACD Extribution & Controls F HVAC zones are a challeng to monitor due to 3/4 height wolls. AtHU/Controls F Estaing distribution/dutwork appear original. Chiller /Controls F Estaing distribution/dutwork appear original. Pumpu/Motors/Compressors G Replaced with Natural Cos in 2018. Boiler and pumps replaced in 2013 Pumping Systems F Photoselectric snoke detector observed only. There is no overall building fine dam system in place.		F	considered.
Exercise Doors Image: construction of the second seco	Windows/Louvers	P	Majority of windows original to building and perforn poorly thermally.
Roof Material G Reofing replaced in 2017 Midding Intentor G CMU partitions of Steeping area do no extend full height Walls - Level 1 F CMU partitions of Steeping area do no extend full height Callings - Level 1 P Casework and countentops are in worn condition Doors/Frames/Hardware P Casework and countentops are in worn condition Stairs NA No Elevator Stairs NA No Elevator Specially Systems NA No Elevator MAC, Distribution & Controls F HvAC, Distribution & Controls F Existing distribution/ductwork appear original. Arc conditioning provided by window units. Replaced Windows G Building does not appear to be sprinklered. MAC, Distribution & Controls F Existing distribution/ductwork appear original. Chiller/Controls F Moder Controls Replaced Win Notrol Cost 10:01. Fire Agrinkered G Building does not appear to be sprinklered. Mutaring System F Photoelectric ande datectors observed only. There is no overall building fire dam system in place. Fire Ad	Exterior Doors		Doors at south elevation have exterior steps and are uninsulated with poor weathersealing.
Milding Invalue Product Milding Invalue F CMU partitions of Sleeping area do no extend full height Walls-Level 1 F CMU partitions of Sleeping area do no extend full height Callings-Level 1 P Water stains in ACT of lifes. ACT celling replacement in 2016 Door/Frames/Hordware P Casework and countertops are in worn condition Stains NA No Slain 1 Elector/Ecolotrs NA No Elector Stains NA No Elector Elector/Ecolotrs NA No Elector Childing systems NA No Elector Elector/Ecolotrs NA No Elector Childing Systems F Examp distribution/Actwork repoor original. Childing Systems G Air conditioning provided by window units. Baller/Heat Exchange/Controls G Building does not appear to be sprinklered. Pumply Motor/Compressors G Building does not appear to be sprinklered. Fire Alarm System F Photoelectric smoke detector subserved only. There is no overall building fire adom system in ploce. Enviroe Doors F			
Floors - Level 1 G Walls - Level 1 F CMU partitions at Sleeping area do no extend full height Calings - Level 1 P Water strins in ACI of office. ACT ceiling replacement in 2016 Doors/Frames/Hordware P Casework and countertops are in worn condition. Strin NA No Elevator Elevators/Escalators NA No Elevator Specially Systems NA No Elevator Bulding Systems NA No Elevator Bulding Systems NA No Elevator PMAC Josthulon & Centrols F HVAC zones are a challenge to monitor due to 3/4 PMU/Controls F Existing distribution/dictork-dappear original. Chiler / Controls NO Air conditioning provided by window units. Boller/Heat Exchange/Controls G Replaced with Naturel Gas in 2016. Baler and pumps replaced in 2013 Fire Sprinklar/Standpipe Systems NO Building does not appear to be sprinklared. New water line to building and upgrades to front and plumbing service. Emergency Power / Lighting Systems Einergency Power / Lighting Systems E Emergency power fron diacctard naturel gas generater (2018). ElevicarD Dirichubion G Power Wring G Tell Alors System F Exterior Doors from carrider and dayroon have and	Roof Material	G	Roofing replaced in 2017
Floors - Level 1 G Walls - Level 1 F CMU partitions at Sleeping area do no extend full height Calings - Level 1 P Water strins in ACI of office. ACT ceiling replacement in 2016 Doors/Frames/Hordware P Casework and countertops are in worn condition. Strin NA No Elevator Elevators/Escalators NA No Elevator Specially Systems NA No Elevator Bulding Systems NA No Elevator Bulding Systems NA No Elevator PMAC Josthulon & Centrols F HVAC zones are a challenge to monitor due to 3/4 PMU/Controls F Existing distribution/dictork-dappear original. Chiler / Controls NO Air conditioning provided by window units. Boller/Heat Exchange/Controls G Replaced with Naturel Gas in 2016. Baler and pumps replaced in 2013 Fire Sprinklar/Standpipe Systems NO Building does not appear to be sprinklared. New water line to building and upgrades to front and plumbing service. Emergency Power / Lighting Systems Einergency Power / Lighting Systems E Emergency power fron diacctard naturel gas generater (2018). ElevicarD Dirichubion G Power Wring G Tell Alors System F Exterior Doors from carrider and dayroon have and	nah		
Product P CMU partitions of Sheping area do no extend full height Ceilings - Level 1 P Water stains in ACT of office. ACT ceiling replacement in 2016 Doors // Franss / Hardware P Casework and countertops are in worn condition Stains NA No Stains Dathin Furnishing P Casework and countertops are in worn condition Stains NA No Stains Dathon Systems Reploced with Noturel Case on a challengte to monitor due to 3/4 Phathon Systems Reploced with Noturel Case in 2016. Bailer and pumps reploced in 2013 Pumbing Systems/Fistures G New water line to building fine adm system in pluce Dathong Devenced F Photoslectric stake datectors observed only. There is no overall building fine adm system in pluce Electrical Distribution G Emergency Power / Lighthing Systems		6	
Walk - Level 1	Floors - Level I		CMU partitions at Sleaning area do no extend full
Calings - Level 1 · replacement in 2016 Dears/Frams/Hordware P Casework and countertops are in worm condition Suits NA No Stairs Elevator/Escolators NA No Stairs Suits NA No Stairs Elevator/Escolators NA No Elevator Spacially Systems NA No Elevator MUXC Distribution & Controls F HVAC Zones are a challenge to monitor due to 3/4 HVAC Distribution & Controls F Existing distribution/devok appear original. Childre/Controls F Existing distribution/devok appear original. Childre/Controls G Replaced with Natural Cas in 2016. Boiler and pumps replaced in 2013 Pumpi/Motors/Compresson G New water line to building and upgrades to front and pumpis replaced in 2013 Pumbing Systems/Futures G New water line to building and upgrades to front and pumpi replaced in 2016. Elevical F Photoslectric snoke detectors observed only. There is no overall building for alarm system in place. Elevical Distribution G Energency power from dedicated natural gas generator (2018). Elevical Dist	Walls - Level 1		height
Descriptions/Horkware P Cosework and countertops are in wom condition Stairs NA No Stairs Stairs NA No Stairs Building Systems NA No Elevator Building Systems NA No Elevator HVAC Distribution & Controls F HVAC zones are a challenge to monitor due to 3/4 height walk. HVAC Distribution & Controls F Existing distribution/ductwork appear original. Chiller/Controls F Existing distribution/ductwork appear original. Baller/Heart Exchange/Controls G Building does not appear to be sprinklered. Pumping Systems/Fixtures G Building and user to be sprinklered. Strike Standapips Systems F Photoelectric snota detector sobarved only. There is no overall building free dorm system in place. Bidding Systems/Fixtures E Emergency Power from duckcied natural gos generator (2018). Entrical Distribution G Photoelectric snota detectors observed only. There is no overall building free dorm system in place. Electrical Distribution G Energency Power from corridor and dayroom have on step to grade Electrical Distribution G <td< td=""><td>Ceilings - Level 1</td><td></td><td>replacement in 2016</td></td<>	Ceilings - Level 1		replacement in 2016
P Casework and counterpop are in wom condition Stairs NA No Elevator Elevator/Escolators NA No Elevator Specially Systems NA No Elevator Building Systems P HVAC Distribution & Controls HVAC Distribution & Controls F HVAC cones are a chillenge to monitor due to 3/4 height walls. AHU/Controls F Existing distribution/duetwork appear original. Chiller/Controls NO Air conditioning provided by window units. Boild/Hat Eschange/Controls G Replaced with Natural Cas in 2016. Bailer and pumps replaced in 2013 Pumps/Nators/Compressors G New water line to building and upgrades to front end plumbing service. Building Elevatord F Photeelectric structure from dedicated natural gas generator (2018). Energency Power/Lighting Systems E Lighting converted to LED in 2016. Elevical Distribution G Proteelectric structure from dedicated natural gas generator (2018). Lighting Systems E Lighting converted to LED in 2016. Elevical Distribution G Security Systems Tel/Data Systems G	Doors/Frames/Hardware	Р	
Stairs NA No Stairs Elevators/Escalators NA No Elevator Specially Systems NA No Elevator Building Systems NA No Elevator HVAC Distribution & Controls F HVAC zones are a challenge to monitor due to 3/4 height walls. AtU/Controls F Existing distribution/Actework appear original. Boilder/Heat Eschange/Controls G Air conditioning provided by window units. Boilder/Heat Eschange/Controls G Building does not appear to be sprinklered. Pumps/Motors/Compressors G Building does not appear to be sprinklered. Pumps/Motors/Compressors G New water line to building and upgrades to front end pumbing systems/Fibrures Punding Elevation F Photoelectric smake detectors observed only. There is no overall building fire alarm system in place. Emergency Power/Lighting Systems E Emergency Power/Coll bail Elevator Distribution G Security Systems G Security Systems G Elevator Distribution G Security Systems G Stetrior Doors from corridor and dayroom have one step to gra	Built-in Furnishings	P	
Specially Systems NA Building Systems HVAC zones are a chillinge to monitor due to 3/4 height walls. HVAC Distribution & Controls F Bailer/Heat Exchange/Controls G Building Systems G Building Systems/Fictures G Building Systems/Fictures G Building Systems/Fictures G Building Systems/Fictures F Photoelectric smake detectors observed only. There is no overall building free dam system in place. Emergency Power/Lighting Systems E Lighting Systems E Lighting Systems G Security Systems C Electrical Distribution G Security Systems			
Building Systems F HVAC zones are a challenge to monitor due to 3/4 height walk. HVAC Distribution & Controls F Existing distribution/ductwork appear original. Chiller/Controls NO Air conditioning provided by window units. Boiler/Heart Exchange/Controls G Replaced with Natural Gas in 2016. Boiler and pumps replaced in 2013 Pumps/Motors/Compressors G Building does not appear to be sprinklered. Plumbing Systems/Fotures G New water line to building and upgrades to front end plumbing service. Emergency Power/Lighting Systems E Emergency power fron dedicated natural gas generator (2018). Electrical Distribution G Emergency power fron dedicated natural gas generator (2018). Electrical Distribution G Enterior Doors fron corridor and dayroom have one step to grade. Electrical Distribution G Exterior Doors fron corridor and dayroom have one step to grade. Merical Circulation (Corridors) PC Door hardware should be lever type Horizontal Circulation (Corridors) PC Non existent Merical Circulation (Corridors) PC Non existent Merical Circulation (Ramps) MA Non existent	Elevators/Escalators	NA	No Elevator
Fire HVAC Distribution & Controls F HVAC Distribution & Controls F AHU/Controls F Existing distribution/ductwork appeor original. Aric conditioning provided by window units. Boiler/Heat Exchange/Controls G Replaced with Nature Ocs in 2016. Boiler and pumps replaced in 2013 Pumps/Motors/Compressors G Building does not appeor to be sprinklered. Pumping Systems/Fixtures G Building does not appeor to be sprinklered. Building Systems/Fixtures G New water line to building and upgrades to front end plumbing service. Building Electrocol F Photoelectric smake detectors observed only. There is no overall building free alarm system in place. Emergency Power/Lighting Systems E Lighting converted to LED in 2016. Electrical Distribution G Security Systems G Verew Wring G Security Systems C Exterior Doors from corridor and dayroom have one step to grade Interior Doors NC Exterior Doors from corridor and dayroom have one step to grade Interior Doors NC Toilets Showers Non-compliant / Single sex. Drinking Fountatins NA Vertical C		NA	
F HVAC Distribution & Controls F HVAC Distribution & Controls F Existing distribution/ductwork appear original. AHU/Controls NO Air conditioning provided by window units. Boiler/Heat Exchange/Controls G Replaced with Nature Ocs in 2016. Bailer and pumps replaced in 2013 Pumps/Motors/Compressors G Building does not appear to be sprinklered. Pumbing Systems/Fixtures G New water line to building and upprades to front end plumbing service. Building Electrocol Fire Sprinkler/Standpipe Systems F Plunching Systems/Fixtures G New water line to building readom system in place. Emergency Power/Lighting Systems E Emergency power from dedicated natural gas generator (2018). Lighting Systems E Lighting converted to LED in 2016. Electrical Distribution G F Power Wrining G Security Systems Security Systems C Exterior Doors from corridor and dayroom have one step to grade Interior Doors NC Exterior Doors from corridor and dayroom have one step to grade Interior Doors NC Door harchware should be lever type			
HYAC Distribution & Controls F height wells. AHU/Controls F Existing distribution/ductwork appear original. Chiller/Centrols NO Air conditioning provided by window units. Boiler/Heat Exchange/Controls G Replaced with Natural Gas in 2016. Boiler and pumps replaced in 2013 Pumps/Motors/Compressors G Building does not appear to be sprinklered. Fire Sprinkler/Standpips Systems NO Building does not appear to be sprinklered. Moding Electrod F Photoelectric smake detectors abserved only. There is no overall building fire alorm system in place. Emergency Power/Lighting Systems E Emergency power from dedicated natural gas generator (2018). Lighting Systems E Lighting converted to LED in 2016. Electrical Distribution G Security Systems / Credenticled Access Operer Wring G Security Systems / Credenticled Access Modical Circulation (Corridors) RC Exterior Doors from corridor and doyroom have one step to grade Marical Circulation (Corridors) RC Toellets Showers Non-compliant / Single sex. Motical Circulation (Corridors) NC Toelets Showers Non-compliant / Single sex. Marcal Circulation (Ramps) NA Vertical Circulation (Ramps) Vertical Circulation (Ramps) NA Streader Romageme	Building Systems		
AHU/Controls F Existing distribution/ductwork oppear original. Chille/Controls NO Air conditioning provided by window units. Boiler/Heat Exchange/Controls G Replaced with Nature Gas: 10216. Beiler and pumps replaced in 2013 Pumps/Motors/Compressors G Building does not appear to be sprinklered. Fire Sprinkler/Standpipe Systems NO Building does not appear to be sprinklered. Plumbing Systems/Fiotures G New water line to building and upgrades to front end plumbing service. Building Electrical F Photoelectric smoke detectors abserved only. There is no overall building free dam system in place. Emergency Power/Lighting Systems E Lighting converted to LED in 2016. Electrical Distribution G Security Systems G Very Systems E Electrical Distribution G Security Systems ME/ADA Exterior Doors from corridor and doyroom have one step to grade Interior Doors NC Exterior Doors from corridor and doyroom have one step to grade Interior Doors NC Tolets Showers Non-complicat / Single sex. Drinking Fountations NC Non existent	HVAC Distribution & Controls	F	
Chiller/Controls NO Air conditioning provided by window units. Boller/Heart Exchange/Controls G Replaced with Natural Gas in 2016. Bailer and pumps replaced in 2013 Pumps/Motors/Compressors G Building does not appear to be sprinklered. Pumps/Motors/Compressors G Building does not appear to be sprinklered. Plumbing Systems/Futures G New water line to building and upgrades to front end plumbing service. Building Electrical F Photoelectric smake detectors observed only. There is no overall building fire alarm system in place. Emergency Power/Lighting Systems E Emergency power fron dedicated natural gas generator (2018). Electrical Distribution G Entergency power fron dedicated natural gas generator (2018). Electrical Distribution G Entergency power fron dedicated natural gas generator (2018). Electrical Distribution G Entergency power fron corridor and dayroom have one step to grade ME//DV Esterior Doors fron corridor and dayroom have one step to grade Esterior Doors fron corridor and dayroom have one step to grade Merical Circulation (Corridor.) RC Door hardware should be lever type Horizontal Circulation (Ramp) NA Esterior Doors fro		F	
Boiler/Heat Exchange/Controls G Replaced with Natural Gas in 2016. Boiler and pumps replaced in 2013 Pumps/Motors/Compressors G Fire Sprinkler/Standpipe Systems NO Building does not appear to be sprinklered. Pumbing Systems/Fistures G New water line to building and upgrades to front end plumbing service. Building Electrical F Photoelectric smake detectors observed only. There is no averal building fire alarm system no everal building fire alarm system systems Electrical Distribution G Everance Power Wring G Everance Security Systems F Lighting Sortem and dayroom have one step to grade Exterior Doors NC Everance Everance Nerizon		NO	
Bailer/Heat Exchange/Centrols Pumps replaced in 2013 Pumps/Motors/Compressors G Building does not appear to be sprinklered. Fire Sprinkler/Standpipe Systems NO Building does not appear to be sprinklered. Plumbing Systems/Fiatures G New water line to building and upgrades to front end plumbing service. Building Electrical Fire Alarm System F Photoelectric smoke detectors abserved only. There is no overall building fire alarm system in place. Emergency Power/Lighting Systems E Lighting converted to LED in 2014. Electrical Distribution G Power Wring G Security Systems E Lighting converted to LED in 2014. Electrical Distribution G Power Wring G G Power Wring G Power Wring G Security Systems / Credenticled Access G Power Wring Power Power Promoted and dayroom have one step to grade Mel/ADA Exterior Doors from corridor and dayroom have one step to grade Power Promoted Circulation (Corridors) PA Merizand Circulation (Corridors) NA Power Promoted Power Promoted Power Promoted Power Prom Sont Corridor and dayroom have one step to grade	ennely connois		Replaced with Natural Gas in 2016. Boiler and
Fire Sprinkler/Standpipe Systems NO Building does not appear to be sprinklered. Plumbing Systems/Fatures G New water line to building and upprades to front end plumbing Systems/Fatures Briddage Bestrand F Photoelectric smake detectors abserved only. There is no overall building fire alorm system in place. Ernergency Power/Lighting Systems E Energency power from dedicated natural gas generator (2018). Lighting Systems E Lighting converted to LED in 2016. Electrical Distribution G			pumps replaced in 2013
Building Electrical G New water line to building and upgrades to front end plumbing systems/Fatures Building Electrical Protoelectric smoke detectors abserved only. There is no overall building fire alarm system in place. Emergency Power/Lighting Systems E Emergency Power/Lighting Systems E Electrical Distribution G Power Wring G Security Systems E Lighting converted to LED in 2016. Electrical Distribution G Power Wring G Security Systems G Security Systems G ME/ADA Exterior Doors from corridor and doynoom have one step to grade Merical Circulation (Corridors) RC Netrical Circulation (Corridors) RC National Circulation (Elevators) NA Vertical Circulation (Elevators) NA Vertical Circulation (Elevators) NA Vertical Circulation (Elevators) NA Site Work/CIVL Site Lighting is by building mounted wall fasture, South elevatorny reconstructed wall fasture, South elevatorny reconstructed in 2019 Wastewater Management G Site Lighting P Site Lighting Site Lighting is by building mounted wall fasture, South elevatorn wising lights or grases pointon. Site Lighting P <td></td> <td>-</td> <td></td>		-	
Plumbing Systems/Fotures P Dubling Service. pumbing service. Dublicing Electrical pumbing service. Fire Alarm System F Photoelectric smoke detectors observed only. There is no overall building fire alarm system in place. Emergency Power/Lighting Systems Emergency Power/Lighting Systems E Lighting converted to LED in 2016. Electrical Distribution G Power Wring G Onewer Wring G Tel/Data Systems C Esterior Doors from corridor and doyroom have one step to grade ME/ADX Esterior Doors from corridor and doyroom have one step to grade Interior Doors from corridor and doyroom have one step to grade Interior Doors NC Door hardware should be lever type Horizontal Circulation (Staria) NA Vertical Circulation (Staria) Variad Circulation (Staria) NA Dividing service. Vertical Circulation (Benzers) NC Non existent Site Drainage / Permeability G Sommwert Management Site Unlifes G New Water Line from Street to Building in 2019 Wastewater Management G South	Fire Sprinkler/Standpipe Systems		New water line to building and upgrades to front end
Fire Adam System P no overall building fire alorm system in place. Emergency Power/Lighting Systems E Emergency power from dedicated natural gas generator (2018). Lighting Systems E Lighting converted to LED in 2016. Electrical Distribution G Power Wring G Interior Doors G Security Systems G Interior Doors from corridor and dayroom have one step to grade ME/ADA Exterior Doors from corridor and dayroom have one step to grade Interior Doors NC Door hardware should be lever type Horizanda Circulation (Corridors) NC Door hardware should be lever type Horizanda Circulation (Remps) NA Vertical Circulation (Remps) Vertical Circulation (Remps) NA Toilets Showers Non-compliant / Single sex. Drinking Fountains NC Non existent Signage NC Non existent Signage RC Non existent Signage G Site Utiling is by building mounted wall fixture, Som every reconstructed in 2019 Wastewater Management G Site Lighting is by building mounted wall fixture, Som every reconstructed in 2019 Site Lighting P Site Lighting is by building mounted wall fixture, Som every reconstructed in 2019 Site Lighting P Sitel ligh	Plumbing Systems/Fixtures	G	plumbing service.
Fire Adam System P no overall building fire alorm system in place. Emergency Power/Lighting Systems E Emergency power from dedicated natural gas generator (2018). Lighting Systems E Lighting converted to LED in 2016. Electrical Distribution G Power Wring G Interior Doors G Security Systems G Interior Doors from corridor and dayroom have one step to grade ME/ADA Exterior Doors from corridor and dayroom have one step to grade Interior Doors NC Door hardware should be lever type Horizanda Circulation (Corridors) NC Door hardware should be lever type Horizanda Circulation (Remps) NA Vertical Circulation (Remps) Vertical Circulation (Remps) NA Toilets Showers Non-compliant / Single sex. Drinking Fountains NC Non existent Signage NC Non existent Signage RC Non existent Signage G Site Utiling is by building mounted wall fixture, Som every reconstructed in 2019 Wastewater Management G Site Lighting is by building mounted wall fixture, Som every reconstructed in 2019 Site Lighting P Site Lighting is by building mounted wall fixture, Som every reconstructed in 2019 Site Lighting P Sitel ligh	Building Electrical		
Emergency Power/Lighting Systems E Emergency power from dedicated natural gas generator (2018). Lighting Systems E Lighting converted to LED in 2016. Electrical Distribution G Power Wring G Tel/Dato Systems G Security Systems / Credentialed Access G ME/ADA NC Exterior Doors NC Exterior Doors NC Interior Doors NC Horizontal Circulation (Corridors) NC Proceed Circulation (Corridors) NA Vertical Circulation (Staria) NA Vertical Circulation (Elevators) NA Toilets Showers Non-compliant / Single sex. Drinking Fountains Drinking Fountains NC Non existent Site Unities G Non existent Site Drainage / Permeability G Stermwater Management G Site lighting is by building mounted wall fature, Soth elevation missing lights at agrees points. Site Lighting P Site lighting is by building mounted wall fature, Soth elevation missing lights at agrees points. G	Fire Alarm System	F	Photoelectric smoke detectors observed only. There is
Lighting Systems E Lighting converted to LED in 2016. Electrical Distribution G Power Wring G Info/Loto Systems G Security Systems / Credenticled Access G ME/ADA Exterior Doors from corridor and dayroom have one step to grade Interior Doors NC Exterior Doors from corridor and dayroom have one step to grade Interior Doors NC Exterior Doors from corridor and dayroom have one step to grade Horizontal Circulation (Corridors) PC Horizontal Circulation (Corridors) PC Vertical Circulation (Stars) NA Vertical Circulation (Ramps) NA Vertical Circulation (Romps) NA Tolete Rooms NC Non existent Signage Signage NC Non existent Signage Site Water Management G Site Ushifing Site Ushifing is by building mounted well fature, Soft and public parking spaces are undefined should be cordin missing lights at egress print. Site Lighting Site Lighting is by sources and vehicke turning r	Emergency Power/Lighting Systems	E	Emergency power from dedicated natural gas
Power Wiring G G Fellowater Systems G G Fellowater Systems / Credentialed Access / Credentialed Acces		E	
Power Wiring G G Fellowater Systems G G Fellowater Systems / Credentialed Access / Credentialed Acces	Electrical Distribution	G	
Security Systems / Credentialed Access G ME/ADA NC Exterior Doors from corridor and doyroom have one step to grade Exterior Doors NC Door hardware should be lever type Horizontal Circulation (Corridors) PC Door hardware should be lever type Horizontal Circulation (Corridors) PC Door hardware should be lever type Horizontal Circulation (Corridors) PC Door hardware should be lever type Vertical Circulation (Ramps) NA Vertical Circulation (Blerators) NA Vertical Circulation (Elevators) NA Toilets Showers Non-compliant / Single sex. Drinking Forunkins NC Non existent Signage NC Non existent Signage Sime Water Management G Site Utilities G New Water Line from Street to Building in 2019 Wastewater Management G Site Lighting P Site Lighting is by building mounted well fature, Soft and public parking spaces are undefined should be cordin missing lights at egress points. Siter Grand public parking spaces are undefined should be cordinated with boy access and vehicle turning radius. Front drivewy reconstructed in 2019 Parking / Paved Surfaces G Underground Oil		G	
MS/ADA NC Exterior Doors from corridor and dayroom have one step to grade Interior Doors NC Exterior Doors from corridor and dayroom have one step to grade Interior Doors NC Door hardware should be lever type Horizontal Circulation (Corridors) PC Door hardware should be lever type Horizontal Circulation (Ramps) NA Vertical Circulation (Starig) Vertical Circulation (Elevators) NA Tailets Showers Non-compliant / Single sex. Drinking Fountains NC Non existent Site Drainage / Permedbility G Site Drainage / Permedbility Site Drainage / Permedbility G Site Unlifies Site Unlifies G New Water Line from Street to Building in 2019 Wastewater Management G Site lighting is by building mounted wall fasture, South elevation missing lights at agrees points. Site Lighting P Sitel lighting is by building mounted wall fasture, South elevation missing lights at agrees points. State Lighting P State lighting spaces are undefined should be coordinated with buy access and velicite training radius. Front driveway reconstructed in 2019 Parking / Paved Surfaces G Underground Oil Tank rem		G	
NC Exterior Doors from corridar and doyroom have one step to grade Exterior Doors NC Door hardware should be lever type Harizontal Circulation (Corridon) PC Door hardware should be lever type Harizontal Circulation (Corridon) PC Door hardware should be lever type Harizontal Circulation (Corridon) PC Door hardware should be lever type Vertical Circulation (Ramps) NA Vertical Circulation (Elevators) Vertical Circulation (Elevators) NA Toilets Showers Non-compliant / Single sex. Drinking Fountains NC Non existent Signage NC Non existent Site Works// Circul Site Works// Circul Site Works// Circul Site Works// Circul Site Ushifus G New Water Line from Street to Building in 2019 Wastewater Management G Site Lighting is by building mounted wall fature, Soft leghting spaces are undefined should be coordinated with boy access and vehicle turning radius. Front drivewary reconstructed in 2019 Parking / Paved Surfaces G Underground Oil Tank removal in 2019. Natural Gos Generator with Auto Transfer added in 2018		G	
NC Exterior Doors from corridar and doyroom have one step to grade Exterior Doors NC Door hardware should be lever type Harizontal Circulation (Corridon) PC Door hardware should be lever type Harizontal Circulation (Corridon) PC Door hardware should be lever type Harizontal Circulation (Corridon) PC Door hardware should be lever type Vertical Circulation (Ramps) NA Vertical Circulation (Elevators) Vertical Circulation (Elevators) NA Toilets Showers Non-compliant / Single sex. Drinking Fountains NC Non existent Signage NC Non existent Site Works// Circul Site Works// Circul Site Works// Circul Site Works// Circul Site Ushifus G New Water Line from Street to Building in 2019 Wastewater Management G Site Lighting is by building mounted wall fature, Soft leghting spaces are undefined should be coordinated with boy access and vehicle turning radius. Front drivewary reconstructed in 2019 Parking / Paved Surfaces G Underground Oil Tank removal in 2019. Natural Gos Generator with Auto Transfer added in 2018			
Exterior Doors Itel step to grade Interior Doors NC Door hardware should be lever type Horizontal Circulation (Corridors) PC Horizontal Circulation (Steins) Vartical Circulation (Steins) NA Vertical Circulation (Steins) Site Rooms NC Non existent Site Drainage NC Non existent Site Drainage G Stermwater Management G Site Utiling is by building mounted wall fasture, South elevation missing lights at agrees points. Site Lighting P Site lighting is by building mounted wall fasture, South elevation missing lights at agrees points. Parking / Paved Surfaces G Underground Oil Tank removal in 2019. Natural Cas Generator with Auto Transfer added in 2018.		L.C.	Exterior Doors from corridor and dayroom have one
Intercental Circulation (Corridors) PC Horizontal Circulation (Corridors) NA Vertical Circulation (Stairs) NA Toilet Rooms NC Drinking Fountains NC Signage NC Site Drainage / Permeability G Startwork // arVL Site Drainage / Permeability G New Water Line from Street to Building in 2019 Wastewater Management G Site Lighting P Site Lighting is by building mounted wall facture, South elevation missing lights at egress points. Site Lighting P Staff and public parking spaces are unadifined should be coordinated with buy access on velocitined hould in 2019 Parking / Paved Surfaces G Underground Oil Tank removal in 2019. Natural Gos Generator with Auto Transfer added in 2018	Exterior Doors		step to grade
NA NA Vertical Circulation (Ramps) NA Vertical Circulation (Staira) NA Vertical Circulation (Staira) NA Vertical Circulation (Elevators) NA Drinking Fountains NC Toilett Showers Non-compliant / Single sex. Drinking Fountains NC Signage NC Non existent Signage NC Site Drainage / Permeability G Ster Unlifies G Site Unlifies G Site Unlifies G Site Lighting P Site Lighting P Site Lighting P Saff and public parking spaces are undefined should be coordinated with bay access and vehicle turning radius. Front drivery reconstructed in 2019 Parking / Paved Surfaces G Underground Cill Tank removal in 2019. Natural Gas Generator with Auto Transfer added in 2018	Interior Doors		Door hardware should be lever type
Vertical Circulation (Stairs) NA Vertical Circulation (Elevators) NA Vertical Circulation (Elevators) NA Totale Rooms NC Totale Rooms NC Drinking Fountains NC Non existent Signage Signage NC Non existent Signage Site Drainage / Permeability G Site Drainagement G Site Utilities G Site Utilities G Site Lighting P Site Lighting P Site Lighting South elevation missing lights at agrees points. Parking / Paved Surfaces G Underground Oil Tank removal in 2019. Natural Gas Generator with Auto Transfer added in 2018	Horizontal Circulation (Corridors)		
Warical Circulation (Elevators) NA Toilet Rooms NC Toilets Showers Non-compliant / Single sex. Drinking Fountains NC Non existent Signage NC Non existent Sile Drainage / Permeability G Sile Drainage / Permeability Site Unlines G New Water Line from Street to Building in 2019 Wastewater Management G Site Lighting is by building mounted wall fixture, South elevation missing lights at egress points. Site Lighting P Safe find public parking spaces are undefined should rodus. Front drivewor reconstructed in 2019 Parking / Paved Surfaces G Underground Oil Tank removal in 2019. Natural Gas Generator with Auto Transfer added in 2018			
NC Toilets Showers Non-compliant / Single sex. Drinking Fountains NC Non existent Signage NC Non existent Signage NC Non existent Site Drainage / Permeability G Site Drainage / Permeability Site Drainage / Permeability G Site Unlines Site Unlines G New Water Line from Street to Building in 2019 Wastewater Management G Site Lighting is by building mounted wall fasture, South elevation missing lights at agress points. Site Lighting P Sitel lighting is by building mounted wall fasture, South elevation missing lights at agress points. Site Lighting P Sitel lighting is by ouriding spaces are undefined should be coordinated with bay access and vehicle turning radius. Front drivewy reconstructed in 2019 Parking / Paved Surfaces G Underground Oil Tark removal in 2019. Natural Gas Generator with Auto Transfer added in 2018			
NC Non existent Signage NC Non existent Signage NC Non existent SITEWORK / CVIL Image: Comparison of the second of the			Toilett Showper Non-compliant / Simple and
Signoge NC Non existent Signoge Non existent Image: Comparison of the second s		_	
Stret WORK / CIVIL G Site Drainage / Permeability G Site Drainage / Permeability G Site Unlifies G Wastewater Management G Site Lighting P Site Lighting is to your constructed in 2019 Parking / Paved Surfaces G Underground Oil Tank removal in 2019. Natural Gos Specially Systems G			
Site Drainage / Permeability G Stormwater Management G Site Utilities G Wastewater Management G Site Lighting P Site Lighting Site Lighting is by building mounted wall fasture, South elevation missing lights at egress points. Parking / Paved Surfaces P Specialty Systems G	aignage	160	LIGH BUSIEN
Site Drainage / Permeability G Stormwater Management G Site Utilities G Wastewater Management G Site Lighting P Site Lighting Staff and public parking spaces are undefined should be accordinated with by access and which le huming radius. Front driveway reconstructed in 2019 Parking / Paved Surfaces G Underground Oil Tank removal in 2019. Natural Gas Generator with Auto Transfer added in 2018		1	
Site Unities G G Underground Oil Tank removal in 2019. Natural Gas Generator with Auto Transfer added in 2018		G	
Operation G New Water Line from Street to Building in 2019 Wastewater Management G Site Lighting P Site lighting is by building mounted wall fixture, South elevation missing lights of agress points. Site Lighting P Site lighting is by building mounted wall fixture, South elevation missing lights of agress points. Parking / Paved Surfaces P Staff and public parking spaces are undefined should be accordinated with by access and vehicle turning radius. Front driveway reconstructed in 2019 Specialty Systems G Underground Oil Tank removal in 2019. Natural Gas Generator with Auto Transfer added in 2018		-	
G Site Lighting is by building mounted wall fixture, South elevation missing lights at egress points. Site Lighting P Site lighting is by building mounted wall fixture, South elevation missing lights at egress points. Parking / Paved Surfaces P Staff and public parking spaces are undefined should be accordinated with by accordinated with by accordinated with by accordinated with by accordinated with bus accordi			New Water Line from Street to Building in 2019
Site Lighting P Site Lighting is by building mounted wall fixture, South elevation missing lights of agrees points. Parking / Paved Surfaces P Staff and public parking spaces are undefined should be coordinated with buy access and veilable terming radius. Front driveway reconstructed in 2019 G Underground Oil Tank removal in 2019. Natural Gas Generator with Auto Transfer added in 2018		G	
Parking / Paved Surfaces Parking / Paved Surfaces G Underground Oil Tank removal in 2019 G Underground Oil Tank removal in 2019 Specialty Systems		P	
Specialty Systems Generator with Auto Transfer added in 2018		Р	be coordinated with bay access and vehicle turning
		G	Underground Oil Tank removal in 2019. Natural Gas Generator with Auto Transfer added in 2018
		~	
	regelation	G	



Generally at a 'near new' condition. Appropriate funding and continued routine maintenance will be required to maintain this level.

Generally at a acceptable condition, with some observable wear. Appropriate funding a confinued routine maintenance will be required to maintain this level.

Generally at a minimal acceptable condition, with significant wear. Improveme involving greater then routine maintenance, and additional funding required. Conditions are below acceptable level and require substantial funding and/or considerable maintenance efforts to be improved or replaced.

Not Applicable

NO Not Observed



Conforms with the most current version of Building Code of Maine and ICC/ANSI A117.1 ADA

Partially Compliant Partially confirms with the most current version of the Building Code of Maine or ICC/ANSI A177.1 ADA.

NC Non-Compliant Does not conform with the most current version of the Building Code of Maine or ICC/ANSI A177.1 ADA

Not Applicable

Appendix C

Program

Drawings: Engine 3: New Public Safety Facility Side Addition: Plan Diagrams

Engine 2 Side Addition: Plan Diagrams New Construction: Plan Diagrams

Engine 5 Side Addition: Plan Diagrams

New Public Safety Facility

Space Needs Program Analysis

				Public Access	Fire Access	Shared Fire &	Dispatch	Police Access	-
						Police Access			Subtotoal
	Vestibule			50					
1	Public Lobby		Access to Community Room	400					
υ	Public Toilets		Display cases for Fire & Police Archives	90 86					
	Public Interview Rooms		(2) HC accessible Toilets, drinking fountain(2) Rooms for (4) occupants each	180					
- 1									
	Plan Review	Fire Prevention	1 room for (4) occupants	90					
n n	Main Desk		Greeter for both AFD & APD	100					
_ 1	Multi Desk		Secure safe space but open & welcoming	100					
> †									
-	Community Room		Adjacent to Lobby, Seating for (30) people	360					
	Stamma		Could expand into Training Room (??? Shared Train Chair & Table Storaghe, AV equipment	ing Room)					
fi	Storage Kitchenette		Chair & Table Sloraghe, AV equipment						
-	renemente de la construction de								1,4
1	Fire Administration	FD Public Waiting	Seating for (2) for Fire Administration		60				
		Fire Chief	Seating for (4) Visitors						
		Assistant Fire Chief Fire Prevention Officer	Seating for (4) Visitors Seating for (2) Visitors						
		Fire Executive Assistant	Seating for (2) Visitors		120				
		FPO Assistant	Seating for (2) Visitors		120				
		EMS Coordinator Office	Seating for (2) Visitors						
		Personnel / Training Files Inspection Files	Vertical and horizontal File Cabinets Vertial File Cabinets						
		Conference / Meeting Roc	Table and Seating for 12						
		Work Area	Printer, Copier, Work Table		100				
		Storage	General Office Supply Storage		50				
		EMS Secure Storage	Records, Licenses, QI/QA Vertical File Cabinet		40				
		Iraining Room	Seating for (20), AV inabled, Communications read	people 360 1<					
-	Fire Suppression/EMS	Storage General Office Supply Storage 500 RS Secure Storage 500 RS Secure Storage 500 Storage Records, Licenses, (U)(QA Vertical File Cabinet 400 Training Room Seating for [20], AV inabled, Communications ready 1,000 Stattalian Chief Office Seating for [20], Visitors, / 4 verifical File Cabinet 180 Captain Office Seating for [20], Visitors, / 4 verifical File Cabinet 180 Fire Offices Seating for [20], Visitors, / 4 verifical File Cabinet 180 Fire Offices Storage Road 5,500 General Storage 5,500 Tower Truck [1], Spare engines [2], Forestry Pickup, Comm (2] EMS Ambulances 1,250 Units 323,321, 322 General Storage 300 200 Wash Room / Dirty Room file Is this EMS Decon Room?? 120 Kost Robus / Dirty Room Pils this EMS Decon Room?? 1200 Kost Road 300 200 Kost Road 300 200 Kost Road 300 200 Kost Road 70 Storage of some radio charging stations and a base radio f							
	ine suppression/EMS	Captain Office	Seating for (2) Visitors / 4 vertical File Cabinet						
		FF/EMS Staff Area	Workstation for (3)		180				
		Fire Officers' Area							
-									
	Apparatus Bays		(5) Bays assumed (what apparatus will be here??)		5.500	Tower Truck (1), Spare engine	s (2), Forestry	Pickup, Cor
ц _f	EMS Bays		(2) EMS Ambulances		1,250			1	
צ			(3) Small Vehicles		540	Units 323,321,	322		
	Utility Spaces	Consul Domain			200				
-		General Storage Wash Room / Dirty Room	22 Is this EMS Decon Room22						
-									
		SCBA Fill Area	Need Space for spare Cylinders (30)		280				
		Hose Storage Room							
		Compressor Area							
		Toilet Room off of Bays	221. this Dudie and an air 222			C1		a station and	a hara and
			eels this Kadio parts and repairee			Storage of som	e radio chargin	g stations and	a base radi
		Structural PPE Storage	Structural Coats, Pants, Boots, Helmets, Gloves						
		Work Shop	Grinder, Work Bench, Bench Vise, Tool Storage,						
		SCBA Repair Workshop	Work Bench, Parts Storage, Tool Storage						
		Fire Equipment Storage	Misc Heavy Equipment and Spare Equipment Racks	5					
		EMS Equip Decon Room	Deep Sink, Large wash area, Drying Racks		200				
h	Firefighter Personnel								
	Functions	Day Room			300				
		Full Kitchen & Dining							
		Personal Storage Lockers	?? Staffing – Truck, Engine, Rescue 315 = 36 locke	rs		Current deman	ds require lock	er space for 28	. Does not
		Male Toilet Shower Room Female Toilet /Shower Roo	m						
	Janitor's Closet	Within Fire Department			80				
	Firefighters' Bunk Area	Male	(24) Twin Sized Beds		1,260				
		Female	(8) Twin Sized Beds		430				
	F		Section for (60) AV institut Commission			60 80 80 80 80 80 80 20 20 20 20 20 20 20 20 20 20 20 20 20			
ב	Emergency Operations Center / Training	Furniture Storage	Seating for (60), AV inabled, Communications read Table & Chairs	y .					
ш	Center / Training Center	Tiolets	(2) Unisex						
_		Kitchen area				80			
¥ [Fitness Area		12 Occupants at 55 sf each			660			
∢ ∣	Boiler Poom					200			
	Boiler Room Fire Supression	Sprinkler Room							
E į	Electrical Room					100			
li i	Emergency Electrical Room					80			
n i	Telephone Data Room					120			<i>c</i> -
	Dispatch	Dispatch Center	Controle Positions (8) active (2) future				1.075		2,7.
	orsputen	Communications Equip	Console Positions (8) active (2) future						
-		Toilets (3)							
		Lockers & Showers					180		
4		Kitchenette / Breakroom							
- SIO		Bunk Area							
5		Conference Room Training Office Manager					450	-	
		Directors office							
		Operations Manager's offi					120		
	Dispatch	IT Director office	Currently IT Director's Office adjacent to Conf. RM				120		
Disp		IT Specialist office	Currently IT Specialist's Office in Conf. RM			_			
		Copy Room - Records	LA911 Maintains Personnel & General Files				150		
	-	Admin Kitchenette Janitors Closet	Small sink - counter space - mini fridge - micro LA911 Funds Private Cleaning Service				80		
		Household & Office Suppl	LA911 responsible for it's own inventory						
Edits		Household & Office Suppl Toilets (1)	LA911 responsible for it's own inventory Add one additional toilet (currently 4 within LA911)				80 60		
		Household & Office Suppl Toilets (1) Parking Spaces	LA911 responsible for it's own inventory Add one additional toilet (currently 4 within LA911) 20 Spaces for Dispatch-Admin-Visitors				60		
		Household & Office Suppl Toilets (1)	LA911 responsible for it's own inventory Add one additional toilet (currently 4 within LA911)						

Records Police Administr Off of Lobby with Public Access - (4) workst On or loador win France Actes - (a) vorksam Searing for (2) for Police Administration Searing for (2) visitors Searing for (2) visitors Searing for (2) visitors Searing for (2) visitors General Office space - in the public waiting area Individual Offices (4) - searing for (2) Vistors General Office Supplies 8 lateral file cobinets Finiter / worklobel for projects Searing for 12 PD Public Waiting Chief of Police Executive Assistant Deputy Chief of Police Professional Standards Administrative Assistant Commander Office's Storage 60 180 120 120 120 90 400 48 60 100 440 orage prsonnel Files fork Area onference Room Patrol Functions Workstations for (4) Sergeants Open Workstations for (10) Seats (20) Male (65) Female (15) Male Showers/Toilets Female Showers/Toilets Temale Showers/Toilets Tosters, rifles, breaching equipment, etc. Unizer, for Civilian Staff/Visitor use Tosters, rifles, breaching equipment, etc. (2) bunks for between shift sleeping Patrol Supervisors Officers' Work Area Roll Call Room Locker Rooms 220 550 824 240 390 200 160 60 90 oilet Rooms quipment Room hort Term Sleeping Roo Support Services ш SS Supervisor Equipment Room Workstation Room Office for (2) sergeants Storage and Repair Room Work areas for (8) 180 60 400 υ] Seating for [2] Work areas for [10] [2] Rooms required at 80 SF each Located between interview rooms Office for [1] sergeont Surveillance equipment, crime scene processing, s ublic Waiting quad Room Interview Rooms Observation Roc nal Investigat 70 240 160 60 120 60 90 0 ۵ D Supervisor's Office iretap Room Evidence & Property Adjacent to Prisoner Processing Laboratory is part of Processing Pass Through to Storage 80 220 ce Rec ice Receiving ice Processing 1,000 100 250 Evidence Storage Biological Drying Area Large Item Area Prisoner Processing Adjacent to Sally Port oisoner Processing 350 oxilyzer oking and holding roc Sally Port Loading Dock Supply storage Arms Room Riot Gear storage Indoor Firing Range iized for (3) vehicles, Ambulance Acc Adjacent to Storage 1,400 200 300 250 120 1,400 80 120 130 Range Control Booth Dedicated Mechanical K-9 Office & Kennel (3) firing lanes at 4'-6" by 25 yards with backstop K-9 suppor 12,652 37,808 6,805 44,613 SubTotal TOTAL PUBLIC SAFETY FACILITY SQUARE FOOTAGE Public Parking Flagpoles (50) Spaces, Double Loaded with center drive 15,200 15,200 Subtotal Subtot Fire / EMS Staff Parking [18] Spaces, Double Loaded with center drive Apparatus Bay Approach & Exit Fire Training Build / Training Site / hydrant Hose Lay / Concrete pads for Training Props / Hose Testing 5,265 11,000 45,000 61,26 ш Fuel Dispensing Service Area Generator Pad and Enclos Dumpsters 2,000 500 400 300 -(2) Dumpster on pads with S Subtotal 3,200 Police Vehicles Police Staff Parking Vehicle Impound Area Sally Port Approach/ Exit Loading Dock approach [30] Spaces, Double Loaded with center drive [50] Spaces, Double Loaded with center drive (6) Vehicles, Double Loaded with center drive 8,775 15,200 3,510 2,800 700 30,985 jubTotal Subtotal 110,650 33,195 143,845 Driveways @ 30% TOTAL PUBLIC SAFETY SITE USE SQUARE FOOTAGE

New Public Safety Facility

Space Needs Program Analysis


Appendix C: CONCEPTUAL APPROACH: SITE PLAN

ENGINE 3 [CENTRAL STATION + POLICE DEPARTMENT]: 550 Minot Avenue Multi-Story Building Footprint with Site Parking

PROPOSED SITE PLAN:

- easily phased
- true shared facility with balance between programs
- requires adjacent private property






LEGEND:

PUBLIC POLICE DEPARTMENT FIRE DEPARTMENT 911 / DISPATCH

Appendix C:

SIDE ADDITION: PLAN DIAGRAM

ENGINE 3 [CENTRAL STATION]: 550 Minot Avenue



LOWER LEVEL

LEGEND:

PUBLIC SHARED POLICE DEPARTMENT FIRE DEPARTMENT

December 15, 2020

ENGINE 3 [CENTRAL STATION]: 550 Minot Avenue








PUBLIC SHARED POLICE DEPARTMENT FIRE DEPARTMENT

Appendix C: SIDE ADDITION: PLAN DIAGRAM

ENGINE 3 [CENTRAL STATION]: 550 Minot Avenue



LEGEND:	
---------	--

PUBLIC SHARED POLICE DEPARTMENT FIRE DEPARTMENT SIDE ADDITION: PLAN DIAGRAM

ENGINE 3 [CENTRAL STATION]: 550 Minot Avenue



LEGEND:

PUBLIC
SHARED
POLICE DEPARTMENT
FIRE DEPARTMENT
911 / DISPATCH

Appendix C:

CONCEPTUAL APPROACH: SITE PLAN [ADDITION]

ENGINE 2: 180 South Main Street



facilities study: AUBURN PUBLIC SAFETY BUILDINGS

т т

Appendix C: SIDE ADDITION: PLAN DIAGRAM


ENGINE 2: 180 South Main Street




Appendix C: CONCEPTUAL APPROACH: SITE PLAN [NEW CONSTRUCTION] ENGINE 2: 180 South Main Street

PROPOSED SITE PLAN:

- right sized, new purpose-built facility
- efficient building performance
- least invasive to continued operations during construction
- opportunity to remedy bay drainage issues
- compact footprint; 2 stories
- greatest expense
- drive-thru bay option






December 15, 2020

Appendix C:

NEW CONSTRUCTION: PLAN DIAGRAM


ENGINE 2: 180 South Main Street




16

Appendix C: NEW CONSTRUCTION: PLAN DIAGRAM

ENGINE 2: 180 South Main Street





UPPER LEVEL ALTER 20-22 BEDS

UPPER LEVEL ALTERNATE [2 STORY OPTION]


Appendix C: CONCEPTUAL APPROACH: SITE PLAN [ADDITION / RENOVATION]

ENGINE 5: 651 Center Street

PROPOSED SITE PLAN:

- 3/4 + of existing building is retained
- requires temporary relocation of some Engine 5 living quarters for duration of construction
- aquisition of alternate parking and access recommended to rear or side required
- configuration shown is over setback





Appendix C: SIDE ADDITION: PLAN DIAGRAM

ENGINE 5: 651 Center Street



Appendix D

Meeting Minutes

Kickoff Meeting - August 18, 2020 Meeting No. Two - September 15, 2020 Meeting No. Three - October 13, 2020 Meeting No. Four - November 04, 2020



MEETING MINUTES

date: project: location:	Tuesday, August 18, 2020, 1:00 pm Auburn Public Safety Facilities Study, 2020-0210	
Attendees	Council Chambers, Auburn City Hall	
Anenaces	Derek Boulanger Robert Chase	City of Auburn Facilities Director Fire Chief
		Police Chief
	Jason Moen	
	Paul LeClair	911 Director
	Tim Hall	911
	Barry Sheff	Woodard & Curran
	Megan McDevitt	Woodard & Curran
	James Hebert	Colby Company Engineering
	Julia Tate	Simons Architects
	Austin Smith	Simons Architect

meeting title: **Kickoff Meeting**

1.	Design team toured:	Engine Station 2
		Engine Station 5
		911 Center
		Police Department at City Hall.

2.	Point of Contact for Auburn: Point of Contact for Woodard & Curran Point of Contact for Simons Architects		Derek Boulanger Megan McDevitt Austin Smith
3.	3. Project goals Fire Department		Firefighter Safety. Diesel exhaust adjacent to sleeping spaces Program overflow into apparatus bays No areas for decontamination Viable office and work spaces Revisions to living spaces Bunk rooms that work with staffing and shifts Facilities that accommodate diversity of staff
		911 Center	Location other than basement, center with windows Support space, Office for IT specialist Should fit in with long term plan for FD & PD
		Police Department	Purpose built facility. New building that supports their department for the next 30 to 40 years.
4.	Scope Revision	· · · · ·	ct scope focused specifically on a building by building assessment of all t of the deficiencies are well known, Group requested that more effort be

		allotted to possible solutions. Case in point, an in-depth analysis of City Hall would not be necessary as the building condition is relatively new and placing the PD there was meant as a temporary measure.
5.	Schedule & Deliverables	Goal is to have report finalized for presentation to the City Council in early December of this year. If approved the report and projected costs could be incorporated into the Capital Improvement Plan. Group was mindful of new \$16M High School project. Suggestion was made that the City's bonding history and capacity be investigated.
6.	History of Previous Police	e Department Location
	-	Previous PD building at 67 Minot Ave. PD left in 2009. Building currently abandoned. Moved to two separate levels of City Hall as a temporary five-year measure. Jason mentioned this site, with access on S. Goff St, as dream location for new PD.
7.	Public Safety Campus	Many advantages to have the FD, PD and 911 share a common campus or facility. As the previous W&C / SA study showed, there are many program elements that could be used by all departments while still maintaining security within each department. The EOC for example would benefit from having easy access to all three departments. Also noted that ideally, there would be redundant EOC locations.
		If Engine Station 5 is considered for the campus, travel distance would not be an issue for the PD. The PD does have walk in traffic and this location will not be as accessible to pedestrians.
		If the 550 Minot location is used, the FD training facilities would need to be kept.
8.	911 Center	Could be attached to either FD or PD. Requires sufficient technology such as a hard fiber connection. PD, FD and the Public all need access to the 911 Center.
9.	Background material	Design team, with help from Derek B. will collect as much information as possible, specifically, site and floor plans. Plans will most likely not be cad based but pdf's.
10.	Next meeting time:	Tuesday, September 15, 2020 at 10:00 am in the City Council Chambers



MEETING MINUTES

date:	Tuesday, September 15, 2020, 10:00 am		
project:	Auburn Public Safety Facilities Study, 2020-0210		
location:	Community Room, Auburn	City Hall	
		City of Auburn, Facilities Director	
	Robert Chase	Fire Chief	
	Jason Moen	Police Chief	
	Paul LeClair	L/A 911 Director	
	Tim Hall	L/A 911 Operations Manager	
	Brian Wood	City od Auburn, Assistant City Manager	
	Barry Sheff	Woodard & Curran	
	Megan McDevitt	Woodard & Curran	
	James Hebert	Colby Company Engineering	
	Julia Tate	Simons Architects	
	Austin Smith	Simons Architect	
meeting title:	Meeting No. 2		

Prior to the committee meeting the design team reviewed Engine 5 at 651 Center Street

- 1. No comments or corrections to meeting minutes of August 18, 2020.
- 2. Space program for a combined Public Safety Facility from 2017 was briefly shared. Excel document to be distributed to police and fire chiefs for further review. Site programming with parking count was also reviewed. Parking counts seemed excessively high and should be reviewed further.
- 3. Team presented a graph for a discussion of maintenance and building life with 60 year being the average projected life. Age of current buildings noted with Engine 2 dating to 1952
- 4. Options for Engine 2. Building SF Program for Engine 2 is underway.
 - a. Site constraints noted such as side and rear yard setbacks and an existing watercourse at the SW corner.
 - b. Option 1 was a building addition to the rear. This would place programs adjacent to the apparatus bays and was dismissed.
 - c. Option 2 was a building expansion to the south.
 - d. Option 3 was a new free standing fire station. This has many advantages such as new high performance envelope, being a purpose built new facility. New addition would also easily facilitate phasing.
 - e. If a new freestanding facility is built could additional property to the rear be acquired to facilitate drive through bays?
 - f. Design team will develop both Options 2 & 3 with pros, cons and building cost projections for each.

- 5. Options for Engine 3
 - a. Previous site plan of 2017 for a combined Public Safety Facility reviewed. Full building program and all site parking requirements filled the site almost completely. Given side and rear yard setbacks, lot coverage requirements and waterbody setbacks, full programs would be difficult to accommodate. Plans could also not provide the required fire training ground.
 - b. Option 1 presented with the first phase an addition to the east for new 911, public lobby and FD support. Second phase would be a PD addition to the west over a PD parking deck. Former 911 space would be converted to evidence storage.

The apparatus bays are an obstacle to the connection between the PD and the public entry and FD. As the option is less than ideal, it was eliminated by the committee.

- c. Option 2 is an expansion to the east for a new public entry, FD support, new 911 and a new PD. This expansion would require acquisition the adjacent residential parcel. By having the additional site, full program could be accommodated. There would be more room for site circulation, parking counts and fire training. Status and availability of the parcel is unknown.
- d. Option 3. Renovate Central Station 3 and add to existing building for FD support. PD and 911 Center to be built elsewhere. Three city owned parcels were identified and reviewed. Each have drawbacks such as steep grading or previous use as a landfill.
- e. Chief Chase noted it is important in planning for the FD to move a tower truck to Station 3. This will require a structural upgrade for the bay slab.
- 6. Team proposed the following schedule:

September 15, 2020	10 am Committee workshop	Investigation & program refinement
October 13, 2020	10 am Committee workshop	Refine & focus options
October 27, 2020	10 am Committee workshop	finalize scope & cost projections
November 17, 2020	Issue draft report to Committee	Edit
December 1, 2020	Final report issued	
December 8, 2020	Presentation to the City Council	

7. Project deliverable are as outlined in agenda.



MEETING MINUTES

date:	Tuesday, October 13, 2020, 10:00 am		
project:	Auburn Public Safety Facilities Study, 2020-0210		
location:	Third Floor Conference Roon		
Attendees	Derek Boulanger City of Auburn, Facilities Director		
	Robert Chase	Fire Chief	
	Jason Moen	Police Chief	
	Paul LeClair	L/A 911 Director	
Tim Hall L/A 911 Operations Man		L/A 911 Operations Manager	
	Brian Wood	City of Auburn, Assistant City Manager	
	Megan McDevitt	Woodard & Curran	
	James Hebert	Colby Company Engineering	
Julia Tate Simons Architects		Simons Architects	
	Austin Smith	Simons Architect	

meeting title: Meeting No. 3

- 1. No comments or corrections to meeting minutes of September 15, 2020.
- 2. Interim reports:
 - a. Edits and comments to the Public Safety Facility space program received from PD, FD & 911 Center.
 - b. SA has contacted Becker Structural Engineers (BSE) concerning the floor slab capacity of Engine 3. BSE had prepared a 2013 report and suggested corrective measures. BSE confirmed the existing slab is at its maximum capacity. BSE suggested adding additional structure below or installation of carbon fiber reinforcement to increase capacity.
 - c. Design team will break out projected expenses for the new 911 Center. Team will factor in cost based upon assigned square footage, a portion of the building infrastructure such as mechanical rooms and circulation.
 - d. SA will consult with the Architects Design Group for advice on pricing of 911 call systems and communications.
- 3. Options for Engine 3
 - a. Design Team offered a concept diagram of how Central Station could be converted to a Public Safety Facility. An additional apparatus bay would be added to the west side and would be structured to accommodate the tower truck. Public entry would be position between the FD & PD. PD would include three floors. 911 Center would be on the uppermost level. Vertical circulation and elevators could control access and provide security for each department.
 - b. Two site plans presented, each requiring the acquisition of the adjacent residential parcel. Diagram confirm the building program and required parking can fit on the site.
- 4. Option for Engine 5
 - a. Engine 5 would be renovated internally and a 15 foot addition positioned to the south.

- b. In each fire station Living Areas were distanced from the apparatus bays.
- c. The 15 foot addition expanded the day room, added a private office created a fitness room and added an additional bunk rooms and two private sleeping room. Single sex gang toilets converted to 5 individual toilet shower combinations.
- d. Comments include:
 - i. Ideal bed count is 24
 - ii. Provided a work station for a police officer at this location and Engine 2.
- e. Site plan review:

a. Two options presented:

- i. Low likelihood of acquiring property from Kmart to the south. Better option is the car dealer behind.
- ii. Employees should have 6 parking spots that are defined. Provide public parking spots too.
- 5. Options for Engine 2
- Addition to the existing

New freestanding station positioned to the south

- b. In addition, north portion of the station converted to work support. Living areas separated for work areas by a personal storage locker areas. Lockers would be large 24" by 24" and designed specifically for public safety buildings. Chief Moen suggested the same lockers for the PD. Would also like a power outlet to charge radios. If a built in seat could be added to the front of the lockers, some space could be saved.
- c. Thirteen beds needed initially. If ambulance is stationed at Engine 2, 24 beds requitred.
- d. Chief Chase noted that if four bed rooms worked better, that would be acceptable too.
- e. Site plan reviewed. Comments include:
 - i. New station site plan preferred as it has drive through bays greatly increasing safety.
 - ii. Six staff parking spaces needed plus parking for public.
- f. Group agreed that the new freestanding station is the better option. Addition should be presented and cost estimated to help with the decision making.
- 6. Discussion of Mobil Resource Vehicle currently stored at Public Works. It should be positioned at a fire station or the Public Safety Facility.
- 7. Building Scorecard presented as a method to evaluate the existing buildings.
 - a. Scorecards to incorporate maintenance record provided by Derek B.
 - b. Each scorecard to be prefaces with bullet points or a narrative summing up the condition.
- 8. Schedule:

August 18, 2020	Kick-off Meeting 1:00 pm	
September 15, 2020	10 am Committee workshop	Investigation & program refinement
October 13, 2020	10 am Committee workshop	Refine & focus options
November 4, 2020	10 am Committee workshop	finalize scope & cost projections
November 17, 2020	Issue draft report to Committee	Edit
December 1, 2020	Final report issued	
December 8, 2020	Presentation to the City Council	



MEETING MINUTES

date:	Wednesday, November 04, 2020, 10:00 am		
project:	Auburn Public Safety Facilities Study, 2020-0210		
location:	Third Floor Conference Roon	•	
Attendees	Derek Boulanger	City of Auburn, Facilities Director	
	Robert Chase	Fire Chief	
	Jason Moen	Police Chief	
	Paul LeClair	L/A 911 Director	
	Tim Hall	L/A 911 Operations Manager	
	Brian Wood	City of Auburn, Assistant City Manager	
	Megan McDevitt	Woodard & Curran	
	Barry Sheff	Woodard & Curran	
	Julia Tate	Simons Architects	
	Austin Smith	Simons Architect	

meeting title: Meeting No. 4

- 1. No comments or corrections to meeting minutes of October 13, 2020.
- 2. Updates for Engine 3 (Central)
 - a. Site Plan: specifics of parking numbers and on-duty and swing-in parking to be worked out in next round; 8 impound parking spaces is sufficient. Covered parking and solar canopies to be considered in next phase. Wetlands, buried tank and on-site hydrant access to be addressed in next phase. Show one way traffic flow with gate at sally-port and parking entrance (50-60 ft. from curb).
 - b. Renovation: Reviewed separation of Fire, Police and 911 Call center program block diagrams.
 - c. Cost Estimate: to include security, sprinkler and fire alarm upgrades, gate and perimeter fencing, and cost to relocate fire training facilities
 - d. City of Auburn to see if existing traffic counts exist
 - e. City of Auburn to assess delivery of service impact on Police relocation
- 3. Updates for Engine 2
 - a. Preference expressed for two-story option
 - b. Less technical lockers would suffice for bedrooms
 - c. Security cameras are part of separate budget for this site, coordination of technical needs only
- 4. Updates for Engine 5
 - a. Confirm added office space for officers
 - b. Less technical lockers would suffice for bedrooms, current redundancy with hall lockers to be reviewed
 - c. Security cameras are part of separate budget for this site, coordination of technical needs only
 - d. City of Auburn may approach adjacent property regarding acquisition for Engine 5, but design team will reconfigure parking to fit within property line.

- 5. General / Next Steps:
 - a. Design team to send draft iterations of materials for review and input by email
 - b. City of Auburn to internally review bond servicing and debt capacity, separate from City Council Presentation
 - c. Cost of easement and acquisitions not to be included in estimates.
 - d. Design team to prepare a general model timeline to address potential phasing, existing conditions documentation needs, DEP process, planning and design process and permitting, etc.
 - e. General sustainability goals to be included to address solar and storm water impact (detention tanks)
- 6. Schedule: (Note the following changes in Email of November 12, 2020)

August 18, 2020	<u>Kick-off Meeting 1:00 pm</u>
September 15, 2020	10 am Committee workshop Investigation & program refinement
October 13, 2020	10 am Committee workshop Refine & focus options
November 4, 2020	10 am Committee workshop finalize scope & cost projections
November 30, 2020	Issue draft report to Committee
December 7, 2020	Committee Comments returned to Design Team
December 15, 2020	Finalize Report for submission to City Council
December 21, 2020	Presentation to the City Council
	-